

March 22, 2021

## **Revision History**

Release Device Country Comm.

Commentary

BB-AZ1180

O3/22/21

BB300

Azerbaijan

CCNET

1. Processing of new 1 AZN, 5 AZN and 50 AZN (series 2020, issued in 2021) has been introduced.

- 2. Processing of 10 AZN (series 2018, issued in 2019) has been added.
- 3. Added jam recovery functions (in unloading and dispensing).
- 4. "EMPTY DISPENSER" command has been enabled in 0xCA failure state.
- 5. Implemented CCNET command applicability after bills retraction.

  That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser (attempts to accept bill, dispense bills, possibility of jams in dispenser).
- 6. Maintenance mode (cleaning card) support added.
- 7. MODULE IDENTIFICATION command has been enabled in IDLING state as per CCNET Protocol description.
- 8. Implemented workaround for potential recoverable bezel indication problem in Idling state.
- 9. Detection and rejection of business/plastic cards is improved.
- 10. Greeting message has been changed to "SUZOHAPP".

**BB-AZ1170** 01/05/12 BB300 Azerbaijan CCNET

First release.

## Distinctive features are:

- 1. Barcode recognition.
- 2. Chassis soft download via CCNET to prevent rejection of single bills.
- 3. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.
- 4. Processing of the following options has been implemented:
  - 'LED BV INHIBIT' -> 0 LED is red in BV\_INHIBIT state; 1 LED is turned off
  - 'KEEP BILL' -> 0 bill will be dropped after returning;1 bill will be held
  - 'LOOK TAPE' -> enhanced processing of pass sensor (0 OFF, 1 ON)
  - 'TURN SWITCH' -> switch turning after bill packing (0 OFF, 1 ON)
- 5. Loss of cassette setting "Not Assigned" after RESET has been eliminated.
- 6. Control of thermo heater in metal dispenser has been added.
- 7. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.
- 8. Set higher priority to the indication of "BOX REMOVED" state.
- 9. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).
- 10. Power recovery has been introduced.
- 11. Non-volatile counters for counting all dispensed or unloaded bills have been added.
- 12. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.
- 13. Errors related to setting date/time from B2B keypad in Service mode have been fixed.
- 14. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.
- 15. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.



March 22, 2021

- 16. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.
- 17. Fix for unload in case when some bills were manually removed from the cassette has been brought in.
- 18. Switching to download mode has been prohibited in the following error states: ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV (all failures of Sense-a-Click).
- 19. Software RESET has been prohibited in the following states: ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV (all failures of Sense-a-Click).
- 20. Command "READ BB-DEVICES SERIAL NUMBER" has been added to CCNET.
- 21. BB turns to IDLING through chassis reinitialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.
- 22. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.
- 23. Country code has been replaced with currency code in all internal tables.
- 24. Barcode is prohibited to be stacked to the recycling cassette.
- 25. BB suspends dispensing and reports BOX REMOVED if drop box was removed over dispensing; BB will resume dispensing after drop box replacement.
- 26. Diagnostic has been introduced.
- 27. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.
- 28. FEED LEVEL capability has been introduced.
- 29. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET.
- 30. BB statistics in new format has been introduced.
- 31. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states.
- 32. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch.