

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-CO1191</u>	10/29/21	BB300	Colombia	CCNET
<ol style="list-style-type: none"> Acceptance rate for 2000 COP issued in 2015-2018 has been improved according to the latest samples of street grade bills received from customer. Counterfeits protection has been improved for 50000 COP. Detection and rejection of double bills has been improved for 2000 COP based on scans and the latest samples of street grade banknotes. Rejection of glued banknotes has been improved in High security acceptance mode for 20000 COP issued in 1996-2011. Implemented automatic restoring of the recycling cassette capacity limit after restart (power interruption, reset command etc.). Supported Denomination Set: "SDS-COP7-R6". <p>Limitations:</p> <ol style="list-style-type: none"> Diagnostics is not supported. 				
<u>BB-CO1190</u>	05/21/19	BB300	Colombia	CCNET
<ol style="list-style-type: none"> Acceptance rate for 2000 COP (issued in 2016, 2017) has been improved according to the latest samples of street grade bills. Counterfeits protection has been improved for 20000 COP and 50000 COP based on scans. Detection and rejection of double bills has been improved for 2000 COP (2016, 2017). Overall acceptance rate has been improved. <p>Limitations:</p> <ol style="list-style-type: none"> Diagnostics is not supported. 				
<u>BB-CO1189</u>	03/29/19	BB300	Colombia	CCNET
<ol style="list-style-type: none"> Acceptance rate for 2000 COP (banknotes series 2016, Prefix AE, AF with date and signature 29 DE AGOSTO DE 2017) has been improved based on scans received from customer. <p>Limitations:</p> <ol style="list-style-type: none"> Diagnostics is not supported. 				
<u>BB-CO1188</u>	07/09/18	BB300	Colombia	CCNET
<ol style="list-style-type: none"> Counterfeit protection has been improved based on scans of 50000 COP counterfeits. Implemented workaround for potential recoverable bezel indication problem in Idling state. <p>Limitations:</p> <ol style="list-style-type: none"> Diagnostics is not supported. 				
<u>BB-CO1187</u>	08/18/17	BB300	Colombia	CCNET
<ol style="list-style-type: none"> Processing of 2000 COP (2016, series "AB") has been added. 				

October 29, 2021

2. Overall acceptance rate has been improved.
3. Fixed CCNET command applicability after bills retraction.
That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.

Limitations:

1. Diagnostics is not supported.

<u>BB-CO1186</u>	02/09/17	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Processing of new 2000 COP (2016), 5000 COP (2016) and 10000 (2016) has been introduced. 2. Overall acceptance rate has been improved. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is not supported. 				
<u>BB-CO1185</u>	10/14/16	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Processing of new 50000 COP (2016) has been introduced. 2. Overall acceptance rate has been improved. 				
<u>BB-CO1184</u>	09/09/16	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Processing of new 20000 COP (2016) has been introduced. 2. Overall acceptance rate has been improved. 3. Detection and rejection of suspect 2000 COP (2011) has been improved. 				
<u>BB-CO1183</u>	05/12/16	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Processing of new 100000 COP (2016) has been introduced. Bill table changed ("Bill type 6" has been set to "100000 COP"); DIP Sw.1.7 is set to "100000 COP". 2. Overall acceptance rate has been improved. 				
<u>BB-CO1182</u>	12/30/14	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Rejection of glued bills (of half-genuine / half-fake suspect notes) has been improved. 2. Processing of Barcodes has been improved. 3. Maintenance mode (cleaning card) support was added. 				
<u>BB-CO1181</u>	01/20/14	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Performance improvement to 20000 COP. 2. Acceptance rate of 1000 and 5000 COP has been improved based on the latest samples of bills, printed in 2013. 				
<u>BB-CO1180</u>	08/31/13	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Overall acceptance rate has been improved based on the latest samples of street grade bills. 2. Jam recovery during Unload has been introduced: after jam in lower tract of BB chassis during unloading operation BB returns jammed bill back to corresponding cassette and try to unload the same bill again. This feature has been implemented for 0xE1, 0xE2, 0xE3, 0xE4, 0xE5, 0xE6 error codes. 				

October 29, 2021

3. Jam recovery during Dispense has been introduced: if time-out of bill arriving to the input sensor of dispenser (error code 0xD4) is detected then BB returns jammed bill back to corresponding cassette and try to dispense the same bill again.

<u>BB-CO1170</u>	07/31/12	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Counterfeit protection has been improved based on the latest samples of half-genuine/half-fake suspect notes. 2. Overall acceptance rate has been improved according to the latest samples of street grade bills. 3. FEED LEVEL capability has been introduced. 4. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET. 5. BB statistics in new format has been introduced. 6. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states. 7. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch. 				
<u>BB-CO1159</u>	03/25/09	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Counterfeit protection has been improved according to the latest samples of 5000 and 10000 COP counterfeits. 2. Acceptance of 20000 COP has been improved based on the latest samples of street grade bills. 3. Country code has been replaced with currency code in all internal tables. 4. Diagnostic command has been introduced (see MAN_CCNET d7 Rev.2.5.1). 5. Problem with barcodes stacked to the Escrow cassette (must be packed into drop box only) has been fixed. 6. If drop box is removed over dispensing then BB suspends dispensing and reports BOX REMOVED, dispensing will be resumed after drop box replacement. 7. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser. 				
<u>BB-CO1153</u>	03/16/07	BB300	Colombia	CCNET
<ol style="list-style-type: none"> 1. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills. 2. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET. 3. Processing of the following options has been implemented: 'LED BV INHIBIT' -> 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off 'KEEP BILL' -> 0 - bill will be dropped after returning; 1 - bill will be held 'LOOK TAPE' -> enhanced processing of pass sensor (0 - OFF, 1 - ON) 'TURN SWITCH' -> switch turning after bill packing (0 - OFF, 1 - ON) 4. Loss of cassette setting "Not Assigned" after RESET has been eliminated. 5. Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking. 6. Control of thermo heater in metal dispenser has been added. 7. Enhance the algorithm of BB self-testing: if cassette(s) is (are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing. 8. Set higher priority to the indication of "BOX REMOVED" state. 9. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description). 				

October 29, 2021

10. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.
11. BB power recovery feature has been introduced.
12. Non-volatile counters for counting all dispensed or unloaded bills have been added.
13. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.
14. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.
15. Errors related to setting date/time from B2B keypad in Service mode have been fixed.
16. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.
17. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.
18. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.
19. Prohibit switching to download mode in the following error states:
ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.
20. Prohibit performing software RESET in the following error states:
ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.
21. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.
22. Remove the control of stand-by battery.
23. Fix for unload in case when some bills were manually removed from the cassette.
24. BB turns to IDLING through chassis re-initialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.
25. The keeping of correct BB statistics has been brought in (failure counters).
26. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.
27. Processing of new 1000 and 2000 COP issued in 2006 has been introduced.

BB-CO1148	06/17/05	BB300	Colombia	CCNET
------------------	----------	-------	----------	-------

1. Metal bezel support is implemented (without influence on the acceptance rate).
2. Barcode recognition is included.
3. Jam (credit loss) in case when two bills are inserted one after another is eliminated.
4. Control of centering mechanism is improved (sticking of "jaws" in validating head is eliminated).
5. Chassis software download via CCNET is supported.
6. CCNET interface has been updated:
 - command for chassis software download has been added;
 - "Extended Identification" command has been included;
 - such option as turn to main program's download stage from "BV Failure" and "BV_Box_Removed" states has been added.
7. Short coupons (tickets, business cards, vouchers) returning has been improved: the object (coupon) was not moved out enough during returning to let the user extract it, now the issue is resolved based on coupon size 85mm * 53mm.
8. Bill drop during rejecting or returning has been eliminated.