

# Revision History

March 18, 2013

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
1	<b><u>BB-EU1181</u></b>	FL-EU7AAJ1-2.81-BB.hex	03/18/13	BB	Europe	CCNET
<p>Commentary</p> <p>1.Processing of new 5 EUR to be issued in 2013 has been introduced. 2. Performance improvement to 5, 20 and 50EUR.</p>						
2	<b><u>BB-EU1180</u></b>	FL-EU7AAJ1-1.80-BB.hex	10/11/12	BB	Europe	CCNET
<p>Commentary</p> <p>1.During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch. 2.Jam recovery during Unload has been introduced: after jam in lower tract of BB chassis during unloading operation BB returns jammed bill back to corresponding cassette and try to unload the same bill again. This feature has been implemented for 0xE1, 0xE2, 0xE3, 0xE4,0xE5, 0xE6 error codes. 3.Jam recovery during Dispense has been introduced: if time-out of bill arriving to the input sensor of dispenser (error code 0xD4) is detected then BB returns jammed bill back to corresponding cassette and try to dispense the same bill again.</p>						
3	<b><u>BB-EU1172</u></b>	FL-EU7AAJ1-1.72-BB.hex	08/13/12	BB	Europe	CCNET
<p>Commentary</p> <p>Performance improvement to 20 EUR.</p>						
4	<b><u>BB-EU1170</u></b>	FL-EU7AAJ1-1.70-BB.hex	08/31/11	BB	Europe	CCNET
<p>Commentary</p> <p>1. Acceptance of 200 EUR has been improved. 2. BB statistics in new format has been introduced.</p>						
5	<b><u>BB-EU1165</u></b>	FL-EU7AAJ1-1.65-BB.hex	09/15/10	BB	Europe	CCNET
<p>Commentary</p> <p>1. FEED LEVEL capability has been introduced. 2. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET. 3. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states. 4. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch. 5. Overall acceptance has been improved according to the latest samples of street grade bills.</p>						
6	<b><u>BB-EU1159</u></b>	FL-EU7AAJ1-1.59-BB.hex	09/29/08	BB	Europe	CCNET
<p>Commentary</p> <p>Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.</p>						
7	<b><u>BB-EU1158</u></b>	FL-EU7AAJ1-1.58-BB.hex	06/04/08	BB	Europe	CCNET
<p>Commentary</p> <p>1. Diagnostic command has been introduced (see MAN_CCNET d7 Rev.2.5.1). 2. Problem with barcodes stacked to the Escrow cassette (must be packed into drop box only) has been fixed. 3. If drop box is removed over dispensing then BB suspends dispensing and reports BOX REMOVED, dispensing will be resumed after drop box replacement.</p>						
8	<b><u>BB-EU1154</u></b>	FL-EU7AAJ1-1.54-BB.hex	05/07/07	BB	Europe	CCNET
<p>Commentary</p> <p>Bill processing has been corrected in order to prevent acceptance of folded 10 &amp; 20 EUR with 5 EUR credit.</p>						

No	Item No.	File Name	Release			Comm. Protocol	Page
			Date	Device	Country		
			<b>Commentary</b>				
9	<b><u>BB-EU1153</u></b>	FL-EU7AAJ1-1.53-BB.hex	01/31/07	BB	Europe	CCNET	
		<ol style="list-style-type: none"> <li>1. BB turns to IDLING through chassis reinitialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.</li> <li>2. The keeping of correct BB statistics has been brought in (failure counters).</li> <li>3. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.</li> </ol>					
10	<b><u>BB-EU1152</u></b>	FL-EU7AAJ1-1.52-BB.hex	06/27/06	BB	Europe	CCNET	
		<ol style="list-style-type: none"> <li>1. Prohibit switching to download mode in the following error states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.</li> <li>2. Prohibit performing software RESET in the following error states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.</li> <li>3. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.</li> <li>4. Remove the control of stand-by battery.</li> <li>5. Fix for unload in case when some bills were manually removed from the cassette.</li> </ol>					
11	<b><u>BB-EU1151</u></b>	FL-EU7AAJ1-1.51-BB.hex	04/26/06	BB	Europe	CCNET	
		<ol style="list-style-type: none"> <li>1. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills.</li> <li>2. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.</li> <li>3. Processing of the following options has been implemented: 'LED BV INHIBIT' -&gt; 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off 'KEEP BILL' -&gt; 0 - bill will be dropped after returning; 1 - bill will be held 'LOOK TAPE' -&gt; enhanced processing of pass sensor (0 - OFF, 1 - ON) 'TURN SWITCH' -&gt; switch turning after bill packing (0 - OFF, 1 - ON)</li> <li>4. Loss of cassette setting "Not Assigned" after RESET has been eliminated.</li> <li>5. Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking.</li> <li>6. Control of thermo heater in metal dispenser has been added.</li> <li>7. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.</li> <li>8. Set higher priority to the indication of "BOX REMOVED" state.</li> <li>9. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).</li> <li>10. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.</li> <li>11. BB power recovery feature has been introduced.</li> <li>12. Nonvolatile counters for counting all dispensed or unloaded bills have been added.</li> <li>13. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.</li> <li>14. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.</li> <li>15. Errors related to setting date/time from B2B keypad in Service mode have been fixed.</li> <li>16. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.</li> <li>17. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.</li> <li>18. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.</li> </ol>					

No	Item No.	File Name	Release		Country	Comm. Protocol	Page
			Date	Device			
			Commentary				
12	<b><u>BB-EU1148</u></b>	FL-EU7AAJ1-1.48-BB	04/27/05	BB	Europe	CCNET	3
		Bill table was corrected; bill drop during rejecting or returning has been eliminated					
13	<b><u>BB-EU1147</u></b>	FL-EU7AAJ1-1.47-BB	04/14/05	BB	Europe	CCNET	
		Error in download procedure of chassis software via CCNET was fixed					
14	<b><u>BB-EU1746</u></b>	FL-EU7AAJ1-1.46-BB	04/11/05	BB	Europe	CCNET	
		Chassis soft download via CCNET was added; short bill returning was improved; CCNET interface was updated by adding the command for chassis soft download + comm and 'Extended Identification' + turn to download from 'BV_Failure'&'BV_Box_Removed' states					
15	<b><u>BB-EU1744</u></b>	FL-EU7AAJ1-1.44-BB	03/04/05	BB	Europe	CCNET	
		Jam prevention;barcode recognition and metal bezel support have been implemented					
16	<b><u>BB-EU1742</u></b>	FL-EU7AAJ1-1.42-BB	02/02/05	BB	Europe	CCNET	
		First release for new hardware					