

Revision History

May 13, 2013

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
1	<u>BB-EUDKSE1180</u>	FL-EU5DK5SE5AAJ1-1.80-BB.h	05/13/13	BB	Euro + Denmark + Sweden	CCNET
		Commentary				
		First release for European Union + Denmark + Sweden.				
		1. Processing of new 5 EUR issued in 2013 has been introduced.				
		2. Performance improvement to 5, 10, 20 and 50 EUR.				
		Distinctive features are:				
		1. Barcode recognition.				
		2. Chassis soft download via CCNET.				
		to prevent rejection of single bills.				
		3. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.				
		4. Processing of the following options has been implemented:				
		'LED BV INHIBIT' -> 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off				
		'KEEP BILL' -> 0 - bill will be dropped after returning; 1 - bill will be held				
		'LOOK TAPE' -> enhanced processing of pass sensor (0 - OFF, 1 - ON)				
		'TURN SWITCH' -> switch turning after bill packing (0 - OFF, 1 - ON)				
		5. Loss of cassette setting "Not Assigned" after RESET has been eliminated.				
		6. Control of thermo heater in metal dispenser has been added.				
		7. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed,				
		software has to skip the algorithm of "device recovery after POWER DOWN"				
		and turn to the regular self-testing.				
		8. Set higher priority to the indication of "BOX REMOVED" state.				
		9. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING,				
		DISABLED, ESCROW states (according to "CashCode NET" description).				
		10. Power recovery has been introduced.				
		11. Nonvolatile counters for counting all dispensed or unloaded bills have been				
		added.				
		12. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS"				
		have been included to CCNET.				
		13. Errors related to setting date/time from B2B keypad in Service mode				
		have been fixed.				
		14. The following error has been fixed: if remove a cassette from the chassis				
		BB keeps trying to pack bills to that cassette.				
		15. "GET STATUS" command is enable only in IDLING and DISABLED states				
		according to CCNET specification.				
		16. Error with displaying of "Not Assigned" state for recycling cassettes				
		in Service mode has been fixed.				
		17. Fix for unload in case when some bills were manually removed				
		from the cassette has been brought in.				
		18. Switching to download mode has been prohibited in the following error				
		states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and				
		ERROR_OPT_SENS_HV (all failures of Sense-a-Click).				
		19. Software RESET has been prohibited in the following				
		states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and				
		ERROR_OPT_SENS_HV (all failures of Sense-a-Click).				
		20. Command "READ BB-DEVICES SERIAL NUMBER" has been added to CCNET.				
		21. BB turns to IDLING through chassis reinitialization after the following				
		sequence: drop box removal, chassis removal, then chassis				
		replacement and drop box replacement.				
		22. The improved algorithm of drop box initialization has been implemented				
		in order to make sure that BB is always able to determine if drop box is				
		completely attached.				
		23. Country code has been replaced with currency code in all internal tables.				
		24. Barcode is prohibited to be stacked to the recycling cassette.				
		25. BB suspends dispensing and reports BOX REMOVED if drop box was removed				

Commentary

- over dispensing; BB will resume dispensing after drop box replacement.
- 26. Diagnostic has been introduced.
- 27. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.
- 28. FEED LEVEL capability has been introduced.
- 29. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET.
- 30. BB statistics in new format has been introduced.
- 31. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states.
- 32. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch.
- 33. Jam recovery during Unload has been introduced: after jam in lower tract of BB chassis during unloading operation BB returns jammed bill back to corresponding cassette and try to unload the same bill again. This feature has been implemented for 0xE1, 0xE2, 0xE3, 0xE4, 0xE5, 0xE6 error codes.
- 34. Jam recovery during Dispense has been introduced: if time-out of bill arriving to the input sensor of dispenser (error code 0xD4) is detected then BB returns jammed bill back to corresponding cassette and try to dispense the same bill again.