

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-IN1688</u>	06/03/20	BB300	India	CCNET
<ol style="list-style-type: none"> Acceptance rate has been improved based on the latest samples of street grade banknotes for: 10 INR (print 2008, 2010, 2014-2018), 20 INR (print 2010, 2013-2017), 50 INR (print 2018, 2019) and 100 INR (print 2018, 2019). Overall acceptance rate has been improved. <p>Limitations:</p> <ol style="list-style-type: none"> Barcodes processing is disabled. 				
<u>BB-IN1687</u>	11/08/19	BB300	India	CCNET
<ol style="list-style-type: none"> Processing of new 20 INR (2019) has been introduced. Processing of 10 INR (2018) and 100 INR (2018) has been added. Acceptance rate for 20 INR (series 2011), 50 INR (series 2011) and 500 INR (series 2016) improved based on scans received from customer. Acceptance rate has been also improved for 5, 10, 20, 50 and 100 INR issued in 2005, 2006 and 2011. <p>Limitations:</p> <ol style="list-style-type: none"> Barcodes processing is disabled. 				
<u>BB-IN1686</u>	01/30/18	BB300	India	CCNET
<ol style="list-style-type: none"> Acceptance rate for 50 INR (2017) and 200 INR (2017) has been improved based on the latest samples of street grade bills. Implemented workaround for potential recoverable bezel indication problem in Idling state. <p>Limitations:</p> <ol style="list-style-type: none"> Barcodes processing is disabled. 				
<u>BB-IN1685</u>	09/25/17	BB300	India	CCNET
<ol style="list-style-type: none"> Processing of two new bill types 50 INR (2017) and 200 INR (2017) has been introduced based on scans received from customer. Processing of 500 INR (2016) and 2000 INR (2016) has been added. Processing of 500 INR, issued before 2016, has been disabled. Bill table has been modified to include 200 INR and 2000 INR (refer to User's Guide for details). DIP Switches (1.1 – 1.8) settings were changed to add new bill types of 200 and 2000 INR (refer to User's Guide for details). Segregation of banknotes 5, 10, 20 and 50 INR, issued before 2005 year, has been implemented. Processing of 100 INR, issued before 2005, has been disabled. Processing of detection and rejection of mutilated banknotes in High Security mode has been improved. Overall acceptance rate has been improved. "EMPTY DISPENSER" command is enabled in OxC A failure state. Fixed CCNET command applicability after bills retraction. 				

June 3, 2020

That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.

Limitations:

1. Barcodes processing is disabled.

<u>BB-IN1684</u>	04/12/14	BB300	India	CCNET
<ol style="list-style-type: none">1. Rejection of glued, taped, and mutilated bills in High Security mode has been improved.2. Processing of 1000 INR has been disabled because of length restriction for a regular BB300.3. Overall acceptance rate has been improved.4. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.				

Limitations:

1. Barcodes processing is disabled.

<u>BB-IN1680</u>	10/26/12	BB300	India	CCNET
<ol style="list-style-type: none">1. Processing of 1000 INR has been introduced.2. Jam recovery during Unload has been introduced: after jam in lower tract of BB chassis during unloading operation BB returns jammed bill back to corresponding cassette and try to unload the same bill again. This feature has been implemented for 0xE1, 0xE2, 0xE3, 0xE4, 0xE5, 0xE6 error codes.3. Jam recovery during Dispense has been introduced: if time-out of bill arriving to the sensor of dispenser (error code 0xD4) is detected then BB returns jammed bill back to corresponding cassette and try to dispense the same bill again.				

Limitations:

1. Barcodes processing is disabled.

<u>BB-IN1171</u>	08/30/12	BB300	India	CCNET
<ol style="list-style-type: none">1. Acceptance of 5 and 20 INR has been improved based on the latest samples of street grade bills.2. Counterfeit protection has been improved according to the latest samples of suspect 500 INR notes.				

<u>BB-IN1170</u>	12/10/11	BB300	India	CCNET
<ol style="list-style-type: none">1. Acceptance of 5, 10, 100 and 500 INR has been improved based on the samples of bills printed in 2010.2. BB statistics in new format has been introduced.3. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states.4. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch.				

<u>BB-IN1161</u>	03/16/10	BB300	India	CCNET
<p>First release.</p> <p>Distinctive features are:</p> <ol style="list-style-type: none">1. Barcode recognition.2. Chassis soft download via CCNET.3. Improved short bill returning.4. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills.5. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.6. Processing of the following options has been implemented: 'LED BV INHIBIT' -> 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off				

- 'KEEP BILL' -> 0 - bill will be dropped after returning; 1 - bill will be held
'LOOK TAPE' -> enhanced processing of pass sensor (0 - OFF, 1 - ON)
'TURN SWITCH' -> switch turning after bill packing (0 - OFF, 1 - ON)
7. Loss of cassette setting "Not Assigned" after RESET has been eliminated.
 8. Control of thermo heater in metal dispenser has been added.
 9. Enhance the algorithm of BB self-testing: if cassette(s) is (are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.
 10. Set higher priority to the indication of "BOX REMOVED" state.
 11. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).
 12. BB power recovery feature has been introduced.
 13. Non-volatile counters for counting all dispensed or unloaded bills have been added.
 14. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.
 15. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.
 16. Errors related to setting date/time from B2B keypad in Service mode have been fixed.
 17. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.
 18. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.
 19. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.
 20. Prohibit switching to download mode in the following error states:
ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.
 21. Prohibit performing software RESET in the following error states:
ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.
 22. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.
 23. Fix for unload in case when some bills were manually removed from the cassette has been implemented.
 24. BB turns to IDLING through chassis re-initialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.
 25. BB statistics (failure counters) is not supported yet.
 26. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.
 27. Country code has been replaced with currency code in all internal tables.
 28. Barcode is prohibited to be stacked to the recycling cassette.
 29. BB suspends dispensing and reports BOX REMOVED if drop box was removed over dispensing;
BB will resume dispensing after drop box replacement.
 30. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.
 31. Diagnostic has been introduced.
 32. FEED LEVEL capability has been introduced.
 33. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET