

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BB-NZ1183</u></b>	03/21/17	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Acceptance rate for polymer 10 NZD (2015) has been improved based on scans and the latest samples of bills received from the field.</li> <li>2. Overall acceptance rate has been improved.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Power recovery is limited because of transparent windows on the banknotes.</li> </ol>				
<b><u>BB-NZ1182</u></b>	05/20/16	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Acceptance rate for 50 NZD (2000) has been improved based on scans and the latest samples of bills received from the field.</li> <li>2. "EMPTY DISPENSER" command has been enabled in 0xCA failure state.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Jam/Power recovery is limited because of transparent windows on the banknotes.</li> </ol>				
<b><u>BB-NZ1181</u></b>	04/15/16	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new polymer 20 NZD (2016), 50 NZD (2016) and 100 NZD (2016) has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. Fixed an error in sensor synchronization that might lead to reduced acceptance rate.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Jam/Power recovery is limited because of transparent windows on the banknotes.</li> </ol>				
<b><u>BB-NZ1180</u></b>	10/13/15	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 5 NZD (2015) and 10 NZD (2015) has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. "CashCode" was changed to "Suzo-Happ Group" everywhere.</li> <li>4. Fixed missing message about unloaded bills before BOX FULL message.</li> <li>5. Processing of Barcodes has been improved.</li> <li>6. Root cause of Infinite initialization cycle found and resolved by putting a boundary check to prevent memory corruption during scanning.</li> <li>7. Improved device behavior if chassis is removed during recycling cassettes re-assignment.</li> <li>8. Improved Jam Recovery feature (in Accepting, Unloading and Dispensing).</li> <li>9. Maintenance mode (cleaning card) support added.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Jam/Power recovery is limited because of transparent windows on the banknotes.</li> </ol>				
<b><u>BB-NZ1170</u></b>	08/27/12	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Overall acceptance rate has been improved based on the latest samples of street grade bills.</li> <li>2. Barcode is prohibited to be stacked to the recycling cassette.</li> </ol>				

3. BB suspends dispensing and reports BOX REMOVED if drop box was removed over dispensing; BB will resume dispensing after drop box replacement.
4. Diagnostic has been introduced.
5. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.
6. FEED LEVEL capability has been introduced.
7. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE
8. CAPACITY LIMIT have been added to CCNET.
9. BB statistics in new format has been introduced.
10. Processing of EMPTY DISPENSER command has been modified to prevent false credit report in non-applicable states.
11. During packing BB tries to reject a bill rather than reports one of the following errors: A8, B5, C2 or E5. This modification allows to prevent jams inside BB switch.

---

<b><u>BB-NZ1154</u></b>	08/27/07	BB300	New Zealand	CCNET
<ol style="list-style-type: none"> <li>1. Acceptance rate of 10 NZD has been improved based on the latest samples of street grade bills.</li> <li>2. Country code has been replaced with currency code in all internal tables.</li> <li>3. BB turns to IDLING through chassis re-initialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.</li> <li>4. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.</li> <li>5. BB statistics (failure counters) is not supported yet.</li> </ol>				

---

<b><u>BB-NZ1152</u></b>	05/17/06	BB300	New Zealand	CCNET
First release for new hardware:				
<ol style="list-style-type: none"> <li>1. Metal bezel support.</li> <li>2. Barcode recognition.</li> <li>3. Jam (credit loss) prevention.</li> <li>4. Chassis soft download via CCNET.</li> <li>5. Improved short bill returning.</li> <li>6. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills.</li> <li>7. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.</li> <li>8. Processing of the following options has been implemented: <ul style="list-style-type: none"> <li>'LED BV INHIBIT' -&gt; 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off</li> <li>'KEEP BILL' -&gt; 0 - bill will be dropped after returning; 1 - bill will be held</li> <li>'LOOK TAPE' -&gt; enhanced processing of pass sensor (0 - OFF, 1 - ON)</li> <li>'TURN SWITCH' -&gt; switch turning after bill packing (0 - OFF, 1 - ON)</li> </ul> </li> <li>9. Loss of cassette setting "Not Assigned" after RESET has been eliminated.</li> <li>10. Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking.</li> <li>11. Control of thermo heater in metal dispenser has been added.</li> <li>12. Enhance the algorithm of BB self-testing: if cassette(s) is (are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.</li> <li>13. Set higher priority to the indication of "BOX REMOVED" state.</li> <li>14. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).</li> </ol>				

---

March 21, 2017

15. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.
16. BB power recovery feature is not supported yet.
17. Non-volatile counters for counting all dispensed or unloaded bills have been added.
18. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.
19. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.
20. Errors related to setting date/time from B2B keypad in Service mode have been fixed.
21. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.
22. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.
23. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.
24. Prohibit switching to download mode in the following error states:  
ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV.
25. Prohibit performing software RESET in the following error states:  
ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV.
26. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.
27. Remove the control of stand-by battery.