

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
1	<u>BB-USEURU1670</u>	FL-US6EU5RU5AAJ6-2.70-BB.h	09/11/14	BB	USA + Euro + Russia	CCNET
		<p>1. Processing of 5 USD issued in 2008 and 100 USD issued in 2013 has been brought in.</p> <p>2. Processing of 5 EUR issued in 2013 and new 10 EUR to be issued in 2014 has been introduced.</p> <p>3. Processing of 500 RUB issued in 2011 and 1000 RUB issued in 2010 has been brought in as well.</p> <p>4. 2 USD, 200 and 500 EUR and 5000 RUB have been excluded from bill processing.</p> <p>5. Old 10, 50, 100, 500 and 1000 RUB have been excluded from bill processing as well.</p> <p>6. Performance improvement to 10, 50, 100, 500 and 1000 RUB.</p> <p>7. Performance improvement to 5, 10, 20 and 50 EUR.</p> <p>8. Overall acceptance rate has been improved based on the latest samples of street grade bills.</p> <p>9. Barcode recognition is no longer supported.</p> <p>10. All the latest software improvements in preparation for the divestiture of Bill-to-Bill product line have been incorporated.</p>				
2	<u>BB-USEURU1154</u>	FL-US7EU7RU6AAJ1-1.54-BB.h	11/21/07	BB	USA + Euro + Russia	CCNET
		<p>First release.</p> <p>Distinctive features are:</p> <p>1. Metal bezel support.</p> <p>2. Barcode recognition.</p> <p>3. Jam (credit loss) prevention.</p> <p>4. Chassis soft download via CCNET.</p> <p>5. Improved short bill returning.</p> <p>6. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills.</p> <p>7. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.</p> <p>8. Processing of the following options has been implemented:</p> <p>'LED BV INHIBIT' -> 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off</p> <p>'KEEP BILL' -> 0 - bill will be dropped after returning; 1 - bill will be held</p> <p>'LOOK TAPE' -> enhanced processing of pass sensor (0 - OFF, 1 - ON)</p> <p>'TURN SWITCH' -> switch turning after bill packing (0 - OFF, 1 - ON)</p> <p>9. Loss of cassette setting "Not Assigned" after RESET has been eliminated.</p> <p>10. Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking.</p> <p>11. Control of thermo heater in metal dispenser has been added.</p> <p>12. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.</p> <p>13. Set higher priority to the indication of "BOX REMOVED" state.</p> <p>14. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).</p> <p>15. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.</p> <p>16. BB power recovery feature has been introduced.</p> <p>17. Nonvolatile counters for counting all dispensed or unloaded bills have been added.</p> <p>18. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.</p> <p>19. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.</p>				

No	Item No.	File Name	Release			Comm. Protocol	Page	2
			Date	Device	Country			
			Commentary					
			20. Errors related to setting date/time from B2B keypad in Service mode have been fixed.					
			21. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.					
			22. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.					
			23. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.					
			24. Prohibit switching to download mode in the following error states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.					
			25. Prohibit performing software RESET in the following error states: ERROR_LINK_SENS_HV, ERROR_MAGN_SENS_HV and ERROR_OPT_SENS_HV.					
			26. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.					
			27. Remove the control of stand-by battery.					
			28. Fix for unload in case when some bills were manually removed from the cassette has been implemented.					
			29. BB turns to IDLING through chassis reinitialization after the following sequence: drop box removal, chassis removal, then chassis replacement and drop box replacement.					
			30. The keeping of correct BB statistics has been brought in (failure counters).					
			31. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.					
			32. Country code has been replaced with currency code in all internal tables.					
			33. BB statistics (failure counters) is not supported yet.					