

- SC Series Bill Validators
- MMI LED Changes


Bulletin #:	FG00206
Bulletin Date:	June 1, 2006
Subject:	MMI LED Changes
Affected Model(s):	All SCXXXX

Summary:

This bulletin covers the changes that have been made to the SC series MMI's LED positioning.

Detail:

Changes have been made to the MMI's LED board. The LED's have been moved lower and the cable lengthened to reduce the stress at the flex point (See pic. B). **This change does not affect the way the LED's function.**



Action:

These changes will take place on all production units starting

Questions should be directed to MEI Technical Support at 1-800-345-8172 or our web site: www.meiglobal.com