## **Revision History**

No	Item No.	File Name Commer		Device	Country	Comm. Protocol
1	BB-CL1172	·	BB.hex 03/26/14 ance rate of 1000 and 2 st samples of street gra	2000 CLP	Chile has been improve	CCNET ed based on
2	BB-CL1171	FL-CL6AAJ1-1.71-E	BB.hex 05/30/11 essing of new 1000 CL		Chile sued in 2011 has	CCNET been introduced.
3	BB-CL1170	<ol> <li>BB st</li> <li>Procedured redit re</li> <li>Durin following</li> </ol>	essing of new 2000 CL tatistics in new format I	P and 20 nas been ENSER states. eject a bi	introduced. command has bee	
4	BB-CL1164	FL-CL6AAJ1-1.64-E Proces	BB.hex 04/28/10 sing of 10000 CLP issu		Chile 09 has been introd	CCNET luced.
5	BB-CL1163	FL-CL6AAJ1-1.63-BB.hex 11/26/09 BB Chile CCNET  1. Processing of 5000 CLP issued in 2009 has been introduced. 2. Overall acceptance rate has been improved based on the latest samples of street grade bills. 3. FEED LEVEL capability has been introduced. 4. Commands SET CASSETTE CAPACITY LIMIT and GET CASSETTE CAPACITY LIMIT have been added to CCNET.				
6	BB-CL1159	<ol> <li>Coun and 1</li> <li>Diagr</li> <li>Probl drop b</li> <li>If dro report</li> <li>Point dispert the late</li> </ol>	CL6AAJ1-1.59-BB.hex 02/03/09 BB Chile CCNET  1. Counterfeit protection has been improved based on the latest samples of 1000 and 10000 CLP counterfeits.  2. Diagnostic command has been introduced (see MAN_CCNET d7 Rev.2.5.1).  3. Problem with barcodes stacked to the Escrow cassette (must be packed into drop box only) has been fixed.  4. If drop box is removed over dispensing then BB suspends dispensing and reports BOX REMOVED, dispensing will be resumed after drop box replacement.  5. Point of reporting "Waiting for bills to be removed" (0x1D 0x01) state during dispensing has been changed from the moment when BB starts moving the last bill to be dispensed from recycling cassette to dispenser to the moment when the last bill to be dispensed enters the dispenser.			
7	BB-CL1154	1000	terfeit protection has b CLP counterfeits. all acceptance has bee	een impr		CCNET e latest samples of atest samples of street
8	BB-CL1153	to pre 2. BB tu	BB.hex 05/07/07 of transparent window vent jams during bill tra urns to IDLING through ence: drop box removal	(plastic 2 ansportat chassis	on in the chassis. reinitialization afte	r the following

and drop box replacement.

3. The keeping of correct BB statistics has been brought in (failure counters).

Release
No Item No. File Name Date Device Country Comm. Protocol Page 2

## Commentary

4. The improved algorithm of drop box initialization has been implemented in order to make sure that BB is always able to determine if drop box is completely attached.

9 **BB-CL1152** FL-CL6AAJ1-1.52-BB.hex 08/17/06 BB Chile CCNET

First release for new hardware:

- 1. Metal bezel support.
- 2. Barcode recognition.
- 3. Jam (credit loss) prevention.
- 4. Chassis soft download via CCNET.
- 5. Improved short bill returning.
- Pass sensor's processing during bill packing has been improved to prevent rejection of single bills.
- 7. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET.
- 8. Processing of the following options has been implemented:
- 'LED BV INHIBIT' -> 0 LED is red in BV\_INHIBIT state; 1 LED is turned off
- 'KEEP BILL' -> 0 bill will be dropped after returning;1 bill will be held
- 'LOOK TAPE' -> enhanced processing of pass sensor (0 OFF, 1 ON)
- 'TURN SWITCH' -> switch turning after bill packing (0 OFF, 1 ON)
- 9. Loss of cassette setting "Not Assigned" after RESET has been eliminated.
- Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking.
- 11. Control of thermo heater in metal dispenser has been added.
- 12. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing.
- 13. Set higher priority to the indication of "BOX REMOVED" state.
- 14. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description).
- 15. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.
- 16. BB power recovery feature is not supported yet.
- Nonvolatile counters for counting all dispensed or unloaded bills have been added.
- 18. Commands "POWER RECOVERY", "EMPTY DISPENSER", "EXTENDED CASSETTE STATUS" have been included to CCNET.
- 19. Size of the transparent window on the banknote has been brought in to be taken into account during transporting of the bill.
- Errors related to setting date/time from B2B keypad in Service mode have been fixed.
- 21. The following error has been fixed: if remove a cassette from the chassis BB keeps trying to pack bills to that cassette.
- 22. "GET STATUS" command is enable only in IDLING and DISABLED states according to CCNET specification.
- 23. Error with displaying of "Not Assigned" state for recycling cassettes in Service mode has been fixed.
- 24. Prohibit switching to download mode in the following error states:

  ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV.
- 25. Prohibit performing software RESET in the following error states:

  ERROR\_LINK\_SENS\_HV, ERROR\_MAGN\_SENS\_HV and ERROR\_OPT\_SENS\_HV.
- 26. Add "READ BB-DEVICES SERIAL NUMBER" command to CCNET.
- 27. Remove the control of stand-by battery.
- 28. Fix for unload in case when some bills were manually removed from the cassette has been implemented.