

# Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BB-KE1184</u></b>	03/19/21	BB300	Kenya	CCNET
<ol style="list-style-type: none"> <li>1. Processing of 50, 100, 200, 500 and 1000 KES (series 2019) has been improved based on the latest samples of street-grade bills received from customer.</li> <li>2. Classification tree of validating constants has been re-calculated to prevent the cross-validation.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance mode (cleaning card) is not supported.</li> </ol>				
<b><u>BB-KE1183</u></b>	07/31/20	BB300	Kenya	CCNET
<ol style="list-style-type: none"> <li>1. Classification tree of validating constants has been rebuilt to prevent the cross-validation.</li> <li>2. Overall acceptance rate has been improved based on the latest samples of street grade bills.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance mode (cleaning card) is not supported.</li> </ol>				
<b><u>BB-KE1182</u></b>	12/21/19	BB300	Kenya	CCNET
<ol style="list-style-type: none"> <li>1. Processing of 50, 100 and 200 KES (series 2019) has been improved based on the latest samples of street grade bills.</li> <li>2. Overall acceptance rate has been improved.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance mode (cleaning card) is not supported.</li> </ol>				
<b><u>BB-KE1181</u></b>	08/20/19	BB300	Kenya	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 50, 100, 200, 500 and 1000 KES (series 2019) has been introduced.</li> <li>2. DIP Switches settings have been modified (refer to User's Guide for details): <ol style="list-style-type: none"> <li>- DIP Switch 1.7 is set to "Old 1000 KES" (was not used previously);</li> <li>- DIP Switch 1.8 is set to "Old 50, 100, 200 &amp; 500 KES" (was not used previously).</li> </ol> </li> <li>3. "EMPTY DISPENSER" command has been enabled in 0xCA failure state.</li> <li>4. Detection and rejection of short coupons/business cards has been improved.</li> <li>5. Implemented workaround for potential recoverable bezel indication problem in Idling state.</li> <li>6. Overall acceptance rate has been improved.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance mode (cleaning card) is not supported.</li> </ol>				
<b><u>BB-KE1180</u></b>	09/16/14	BB300	Kenya	CCNET
New development.				