

# Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BE-EU1113</u></b>	01/04/19	BB300XE_SS	Europe	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 100 EUR (2019) and 200 EUR (2019) has been introduced.</li> <li>2. Counterfeits protection has been improved for 20 EUR.</li> <li>3. Fixed regression which prevented Dispensing Command to be process properly after Power Cut or Failure.</li> <li>4. Implemented workaround for potential recoverable bezel indication problem in Idling state.</li> </ol>				
<b><u>BE-EU1112</u></b>	06/19/17	BB300XE_SS	Europe	CCNET
<ol style="list-style-type: none"> <li>1. Detection and rejection of counterfeits 50 EUR (2002) has been improved based on samples from the field.</li> <li>2. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.</li> <li>3. Fixed chassis software update issues when CPU Memory Stick is used.</li> </ol>				
<b><u>BE-EU1111</u></b>	03/09/17	BB300XE_SS	Europe	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 50 EUR (2017) has been introduced, including support of banknotes with "R"-code, printed by BUNDESDRUCKEREI.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. Detection and rejection of paper infused banknotes has been implemented.</li> <li>4. Implemented support for new BCU (Box Control Unit) with increased stacking force.</li> </ol>				
<b><u>BE-EU1110</u></b>	09/18/15	BB300XE_SS	Europe	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 20 EUR (2015) has been introduced.</li> <li>2. Rejection of folded new 20 EUR has been implemented to prevent cross-validation.</li> <li>3. Detection and rejection of counterfeits has been improved.</li> <li>4. Eliminated false Power recovery report during initialization after BOX FULL message.</li> <li>5. Fixed Power recovery issues during stacking.</li> <li>6. Fixed missing message about unloaded bills before BOX FULL message.</li> <li>7. Corrected processing of Statistics counters for bills, packed into cassette after "Power cut during stacking".</li> <li>8. Improved stacking procedure for bills packed into Drop Box.</li> <li>9. Eliminated false bills rejection accompanied by "CHEATED" message</li> </ol>				
<b><u>BE-EU1109</u></b>	01/26/15	BB300XE_SS	Europe	CCNET
<ol style="list-style-type: none"> <li>1. Rejection of folded new 10 Euro has been improved to prevent cross-validation.</li> <li>2. Overall acceptance has been improved in High Acceptance and High Security modes.</li> <li>3. Detection and rejection of counterfeits has been improved.</li> <li>4. "CashCode" was changed to "Suzo-Happ Group" everywhere.</li> <li>5. Bill length transfer into chassis was implemented.</li> <li>6. DISPENSED message added in case of Dispenser failure during Dispensing operation.</li> <li>7. CCNET_READ_MODULES_ID support became enabled for Idling mode.</li> </ol>				

---

January 4, 2019

8. Credit message added when reset on accepting.
9. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.
10. Optical length filter was implemented.

---

<b>BE-EU1108</b>	07/09/14	BB300XE_SS	Europe	CCNET
------------------	----------	------------	--------	-------

The update includes automatic recovery procedure for extended memory stick communication errors (9B:23 and 9B:16).

---

<b>BE-EU1107</b>	06/16/14	BB300XE_SS	Europe	CCNET
------------------	----------	------------	--------	-------

Processing of new 10 EUR to be issued in 2014 has been introduced.

---

<b>BE-EU1106</b>	02/01/14	BB300XE_SS	Europe	CCNET
------------------	----------	------------	--------	-------

1. Improved extended memory card performance (9B:16).
2. Enhanced status reporting during maintenance.
3. Implemented functionality of Service mode during normal operation and maintenance.
4. Maintenance mode with B2B 100, 200 or 300XE (software adjusts to number of cassettes).
5. Implemented control of maintenance mode via protocol.
6. Improved acceptance of barcodes (improved poor acceptance of long maintenance card due to change in design and shifting barcode position).
7. Improved bill retraction option to be able to retract a combination of long and short bills; reduced jamming.
8. Implemented subsequent presentation of the retracted banknotes to the dispenser opening upon receiving empty dispenser command from the host; this command is applicable when 0xCA failure state.