

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<u>FL-AU2533</u>	10/19/20	(M)FL	Australia	FL_BDP
1. Processing of new 100 AUD (2020) has been introduced.				
<u>FL-AU2532</u>	08/01/19	(M)FL	Australia	FL_BDP
1. Processing of new 20 AUD (2019) has been introduced. 2. Overall acceptance rate has been improved.				
<u>FL-AU2531</u>	04/20/18	(M)FL	Australia	FL_BDP
1. Processing of new 50 AUD (2018) has been introduced. 2. Acceptance rate for 10 AUD (2017) has been improved.				
<u>FL-AU2530</u>	06/13/17	(M)FL	Australia	FL_BDP
1. Processing of new polymer 10 AUD (2017) has been introduced. 2. Overall acceptance rate has been improved.				
<u>FL-AU2529</u>	12/14/16	(M)FL	Australia	FL_BDP
1. Acceptance rate for polymer 5 AUD (2016) and 50 AUD (1995) has been improved based on scans received from the field. 2. Overall acceptance rate has been improved.				
<u>FL-AU2528</u>	02/18/15	(M)FL	Australia	FL_BDP
1. Processing of new polymer 5 AUD (2016) has been introduced. 2. Overall acceptance rate has been improved.				
<u>FL-AU2527</u>	10/15/15	(M)FL	Australia	FL_BDP
Fixed missing rejecting state reporting.				
<u>FL-AU2526</u>	09/11/15	(M)FL	Australia	FL_BDP
1. Overall acceptance rate has been improved based on the latest samples of street grade bills. 2. Analogue Barcode processing has been implemented. 3. Acceptance of Barcode tickets has been improved based on samples received from customer.				
<u>FL-AU2525</u>	04/30/08	(M)FL	Australia	FL_BDP
1. Anti-fishing capability has been improved by implementation of motor swinging during stacking. 2. Stacker cycle has been added in case of rejecting from stacking state. 3. Second byte of the Request Bill Enables command is not masked with 0xFF. 4. Program CRC in the Version string matches Program Signature (Seed = 0).				

5. Acceptance of 20 AUD in High Security mode has been improved.

<u>FL-AU2522</u>	04/30/08	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

1. Processing of "Program signature" command has been brought in.
2. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).

<u>FL-AU2519</u>	11/28/07	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

CRC32 command (0x3B) has been introduced in Service mode in order to provide the way to check authenticity of FL software.

<u>FL-AU2517</u>	07/18/06	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

Acceptance rate has been enhanced according to the latest samples of street money; triple Scan has been removed.

<u>FL-AU2516</u>	07/18/06	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

Acceptance of 5; 10 & 100 AUD has been improved

<u>FL-AU2515</u>	12/22/04	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

ID code (Boot version) has been changed to B319

<u>FL-AU2505</u>	07/19/04	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

Overall acceptance rate has been improved.

<u>FL-AU2504</u>	11/07/03	(M)FL	Australia	FL_BDP
-------------------------	----------	-------	-----------	--------

First release.