

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<u>FL-CL1125</u>	07/27/16	(M)FL	Chile	CCNET
Commentary 1. Overall acceptance rate has been improved. 2. Bill table corrected - unsupported note 500 CLP has been removed from Bill Table; "Bill type 0" has been set to "not used". 3. Greeting message changed to "SUZOHAPP".				
<u>FL-CL1520T</u>	02/17/12	(M)FL	Chile	CCNET
Overall acceptance improved using customer bills and validation head. This software is not available.				
<u>FL-CL1519</u>	06/21/11	(M)FL	Chile	CCNET
1. Processing of new 1000 CLP issued in 2011 has been introduced. 2. Processing of plastic 2000 CLP issued in 2010 has been improved based on the latest samples of street grade bills.				
<u>FL-CL1518</u>	04/15/11	(M)FL	Chile	CCNET
1. Processing of new 2000 CLP and 20000 CLP issued in 2010 has been introduced. 2. Processing of 500 CLP has been disabled.				
<u>FL-CL1616</u>	03/22/10	(M)FL	Chile	CCNET
Processing of new 10000 CLP issued in 2009 has been introduced.				
<u>FL-CL1615</u>	11/02/09	(M)FL Chile		CCNET
Processing of new 5000 Pesos issued in 2009 has been added.				
<u>FL-CL1614</u>	09/02/09	(M)FL	Chile	CCNET
Overall acceptance has been improved based on the latest samples of street grade bills.				
<u>FL-CL1613</u>	04/25/09	(M)FL	Chile	CCNET
1. Processing of new 10000 CLP issued in 2008 has been introduced. 2. DIP switch to enable / disable old 2000 CLP has been brought in. 3. Synchronization by translucent optic signals has been implemented to fix the problem with accepting of transparent plastic 2000 CLP bills.				
<u>FL-CL1612</u>	11/13/08	(M)FL	Chile	CCNET
1. Anti-fishing algorithm has been changed: Synchro sensor is checked now in stacking state instead of Input2 sensor.				

September 18, 2017

2. Stacker cycle has been added in case of rejecting from stacking state.
3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
4. Pause state will occur only if both Input and Aligning sensors covered.
5. 10 sec timeout implemented in Pause state.
6. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.

<u>FL-CL1611</u>	10/29/07	(M)FL	Chile	CCNET
-------------------------	----------	-------	-------	-------

Overall acceptance has been improved according to the latest samples of street grade bills.

<u>FL-CL1610</u>	07/17/07	(M)FL	Chile	CCNET
-------------------------	----------	-------	-------	-------

First release.