

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
FL-CN1122	04/27/21	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Processing of new 5 CNY (2020) has been introduced. 2. Acceptance rate for 1 CNY ('19), 20 CNY ('99, '05, '19), 100 CNY ('99, '05) has been improved. 				
FL-CN1121	12/04/19	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Processing of new 1, 10, 20 and 50 CNY (2019) has been introduced. 2. Detection and rejection of business/plastic cards has been improved. 				
FL-CN1120	04/21/16	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Acceptance rate for 100 CNY (2015) has been improved. 2. Overall acceptance rate has been improved. 				
FL-CN1119	01/29/16	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Processing of new 100 CNY (2015) has been introduced. 2. Overall acceptance rate has been improved. 3. Processing of 1 CNY (1980-1996), 2 CNY (1980, 1990), 5 CNY (1980), 10 CNY (1980), 50 CNY (1980, 1990) and 100 CNY (1980, 1990) has been disabled as per customer request. 4. Bill table changed ("Bill type 1" has been set to "not used"); DIP Sw.1.2 is reserved. 5. Greeting message was changed from "Cash Code" to "Suzo-Happ". 				
FL-CN1718	09/30/09	(M)FL	China	CCNET
Commentary <p>Counterfeit protection has been improved based on the latest samples of glued 100 CNY counterfeits.</p>				
FL-CN1717	11/03/08	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Counterfeit protection has been improved according to the latest samples of glued 10, 20 & 100 CNY bills. 2. Acceptance of 10, 20, 50 & 100 CNY has been improved based on the latest samples of recently issued bills (printed out on new paper). 3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions. 4. Pause state will occur only if both Input and Aligning sensors covered. 5. 10 sec timeout implemented in Pause state. 6. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor. 				
FL-CN1716	04/02/08	(M)FL	China	CCNET
Commentary <ol style="list-style-type: none"> 1. Counterfeit protection has been improved according to the latest samples of glued 10, 20, 50 & 100 CNY counterfeits. 				

April 27, 2021

2. Acceptance rate of 50 & 100 CNY has been improved based on the latest samples of street grade bills.

FL-CN1715 02/20/07 (M)FL China CCNET

Counterfeit protection has been enhanced according to the latest samples of 50 and 100 CNY counterfeits.

FL-CN1714 05/31/06 (M)FL China CCNET

1. Counterfeit protection for 50 CNY has been enhanced according to the latest sample of fake 50 CNY received from the customer.
2. Acceptance of new 5 and 10 CNY issued in 2005 has been improved based on validating head received from the customer.
3. Part number and boot version information have been added to statistics.
4. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".

FL-CN1713 02/09/06 (M)FL China CCNET

1. Acceptance of new 50 & 100 CNY issued in 2005 has been improved according to the latest sample of street money.
2. Counterfeit protection for 10, 50 & 100 CNY has been enhanced based on the latest samples of fake money.

FL-CN1712 10/14/05 (M)FL China CCNET

Processing of new 5, 10, 20, 50, 100 CNY issued in 2005 has been added.

FL-CN1711 07/07/05 (M)FL China CCNET

1. Counterfeit protection has been improved according to latest counterfeit samples.
2. Metal bezel support has been implemented.

FL-CN1710 07/23/04 (M)FL China CCNET

1. Double-bill acceptance has been eliminated.
2. 1 & 2 CNY bills processing and metal bezel support have been included.

FL-CN1508 08/28/03 (M)FL China CCNET

Fixed the problem with POWER UP state when box's removed. New barcode processing.