

September 4, 2018

## **Revision History**

- 2. Bill table changed ("Bill Type 6" has been set to "100000 COP"); DIP Sw.1.7 is set to "100000 COP".
- 3. Overall accepting rate has been improved.
- 4. Detection and rejection of suspect 2000 COP (2011) has been improved.
- 5. Greeting message changed to "SUZOHAPP".

<u>FL-CO1613</u> 05/28/07 (M)FL Colombia CCNET

- 1. Counterfeit protection has been improved according to the latest samples of 5000 and 10000 COP counterfeits.
- 2. Stacker cycle added in case of rejecting from stacking state.
- 3. Rejecting code "Conveying error"(0x64) has been replaced with "Insertion error"(0x60)
- 4. Pause state will occur if both Input and Aligning sensors covered.
- 5. 10 sec. timeout implemented in Pause state.
- 6. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.

FL-CO1612	05/28/07	(M)FL	Colombia	CCNET
Processing of new 1000 & 2000 COP issued in 2006 has been introduced.				
FL-CO1611	03/04/05	(M)FL	Colombia	CCNET
Acceptance of 1000 pesos has been improved; metal bezel is supported.				
FL-CO1610	10/06/04	(M)FL	Colombia	CCNET

First release.