

May 17, 2019

Revision History

| Item No. | | Release Date | Device | Country | Comm. Protocol | |
|----------------------|--|--|-----------------------|--------------------------------|-------------------|--|
| Commentary | | | | | | |
| FL-CO202 | <u>7</u> | 05/17/19 | (M)FL | Colombia | FL_BDP | |
| 1. 2. 3. | Acceptance rate for 2000 COP (issued in 2016, 2017) has been improved based on scans received from customer (for banknotes series 2016, Prefix AE, AF with date "29 DE AGOSTO DE 2017") and also according to the latest samples of street grade bills. Detection and rejection of counterfeits has been improved for 20000 COP and 50000 COP. Diverall acceptance rate has been improved. | | | | | |
| FL-CO202 | <u>5</u> | 02/10/17 | (M)FL | Colombia | FL_BDP | |
| 1. 2. | Processing of new 200 Overall accepting rate | | 00 COP (2016) and i | new 10000 COP (2016) has bee | n introduced. | |
| FL-CO202 | <u>i</u> | 10/14/16 | (M)FL | Colombia | FL_BDP | |
| 1. 2. | Processing of new 500 Overall acceptance rat | • | | | | |
| FL-CO2024 | 1 | 09/14/16 | (M)FL | Colombia | FL_BDP | |
| 1. 2. 3. 4. | Bill table changed ("67 DIP Sw.1.7 is set to "10 Overall acceptance rat Detection and rejectio | rocessing of new 20000 COP (2016) and 100000 COP (2016) has been introduced. Il table changed ("67h" has been set to "100000 COP"); IP Sw.1.7 is set to "100000 COP". IV serall acceptance rate has been improved. It is set to "set to "s | | | | |
| FL-CO202 | <u>1</u> | 01/30/14 | (M)FL | Colombia | FL_BDP | |
| 1. | Processing of 1000 CO | P (2006) has been re- | enabled. | | | |
| FL-CO202 | 2 | 01/30/13 | (M)FL | Colombia | FL_BDP | |
| 1. | Performance improve | ment to 50000 COP. | | | | |
| FL-CO202 | <u>L</u> | 04/27/12 | (M)FL | Colombia | FL_BDP | |
| 1. | Acceptance rate of 200 | 000 COP has been imp | proved based on the | latest samples of street grade | bills. | |
| FL-CO252 | <u>)</u> | 05/21/09 | (M)FL | Colombia | FL_BDP | |
| 1. | Counterfeit protection | n has been improved a | according to the late | st samples of 5000 & 50000 CC | P counterfeits | |
| FL-CO251 | <u>)</u> | 10/23/08 | (M)FL | Colombia | FL_BDP | |



May 17, 2019

- 1. Counterfeit protection has been improved according to the latest samples of 5000 and 10000 COP counterfeits.
- 2. Stacker cycle has been added in case of rejecting from stacking state.
- 3. "Program signature" command has been introduced.
- 4. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).
- 5. Pause state will occur only if both Input and Aligning sensors covered.
- 6. 10 sec timeout implemented in Pause state.
- 7. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.

FL-CO251805/11/07(M)FLColombiaFL_BDP1. Processing of new 2000 COP issued in 2006 has been introduced.

<u>FL-CO2517</u> 09/19/06 (M)FL Colombia FL_BDP

- 1. Counterfeit protection for 20000 COP has been improved according to the latest samples of "2/5 fake 3/5 good" counterfeits.
- 2. Counterfeit protection for 10000 COP has been enhanced based on the latest samples of "1/2 fake 1/2 good" counterfeits.

FL-CO2516 05/26/06 (M)FL Colombia FL_BDP

- 1. Counterfeit protection for 50000 COP has been enhanced according to the latest samples of fake money.
- 2. Acceptance of 5000, 10000 and 20000 COP has been improved to resolve acceptance issues on old FL units.

FL-CO2515 02/22/06 (M)FL Colombia FL BDP

- 1. Protection against glued "half fake half real" counterfeits has been enhanced based on the latest samples of fake money.
- 2. Overall acceptance rate has been improved according to the latest samples of street money.
- 3. Part number and boot version information has been added to statistics.
- 4. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".

FL-CO2505 02/21/03 (M)FL Colombia FL_BDP

First Release