

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<u>FL-PE2120</u>	11/15/18	(M)FL	Peru	FL_BDP
1. Processing of 10 PEN (series 2016), 20 PEN (series 2016) and 100 PEN (series 2015), issued in 2017-2018 and denominated in "SOLES" (not "NUEVOS SOLES"), has been added.				
<u>FL-PE2119</u>	06/27/18	(M)FL	Peru	FL_BDP
1. Counterfeit protection has been improved based on the latest samples of 100 PEN counterfeits.				
<u>FL-PE2118</u>	10/03/16	(M)FL	Peru	FL_BDP
1. Overall acceptance rate has been improved based on scans and the latest samples of bills received from the field. 2. Processing of 10 PEN (2013) and 20 PEN (2013) has been introduced. 3. Greeting message has been changed to "SUZOHAPP".				
<u>FL-PE2117</u>	07/15/14	(M)FL	Peru	FL_BDP
Overall acceptance has been improved.				
<u>FL-PE2116</u>	11/23/12	(M)FL	Peru	FL_BDP
Support of dual bill table has been introduced. Bill table can be selected by DIP Switch 1.8.				
<u>FL-PE2015</u>	12/22/11	(M)FL	Peru	FL_BDP
Processing of new 50 PEN, 100 PEN and 200 PEN issued in 2011 has been introduced.				
<u>FL-PE2514</u>	08/29/11	(M)FL	Peru	FL_BDP
Processing of new 10 PEN and 20 PEN issued in 2011 has been introduced.				
<u>FL-PE2513</u>	10/06/08	(M)FL	Peru	FL_BDP
1. Counterfeit protection has been improved based on the latest samples of 10, 20, 50 and 100 PEN counterfeits. 2. Acceptance of 10, 20, 50 & 100 PEN has been improved according to the latest samples of street grade bills. 3. Stacker cycle has been added in case of rejecting from stacking state. 4. Second byte of the Request Bill Enables command isn't masked with 0xFF mask. 5. Checking of drop box presence has been added for the case when returned bill is held in the entry slot. 6. Pause state will occur only if both Input and Aligning sensors covered. 7. 10 sec timeout implemented in Pause state.				
<u>FL-PE2512</u>	02/08/08	(M)FL	Peru	FL_BDP

November 15, 2018

1. Counterfeit protection has been improved according to the latest samples of 10, 50 & 100 PEN counterfeits.
2. Overall acceptance has been improved based on the latest samples of street grade bills.
3. Processing of "Program signature" command has been brought in.
4. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).

FL-PE2511

07/26/07

(M)FL

Peru

FL_BDP

First release.