

Revision History

Item No.	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol
<u>FL-RO2131</u>	06/08/22	(M)FL	Romania	FL_BDP
<ol style="list-style-type: none"> Processing of new denomination 20 RON (Commemorative, issued in 2021) has been introduced. Processing of 1 RON ('18), 5 RON ('18), 10 RON ('08,'18), 50 RON ('18), 100 RON ('18), 200 RON ('18) has been added based on the latest samples of street grade banknotes received from customer. DIP Switches settings have been changed accordingly to include the new 20 RON, upon discussion with the customer (refer to User's Guide for more details): <ul style="list-style-type: none"> DIP Switch 1.1 is set to enable/disable "1 & 5 RON" (previously was set to "1 RON") DIP Switch 1.2 is set to enable/disable "10 RON" (previously was set to "5 RON") DIP Switch 1.3 is set to enable/disable "20 RON" (previously was set to "10 RON"). Bill Tables #1 & #2 have been modified to include the new denomination 20 RON according to the customer's requirements (refer to User's Guide for more details). <p><u>Bill Tables #1:</u></p> <ul style="list-style-type: none"> Escrow Code "65H" has been set to "5 RON" ("65H" was not previously used) Escrow Code "66H" has been set to "10 RON" (previously was assigned to "5 RON") Escrow Code "67H" has been set to "20 RON" (previously was assigned to "10 RON"). <p><u>Bill Tables #2:</u></p> <ul style="list-style-type: none"> Escrow code "64H" has been set to "5 RON" ("64H" was not previously used) Escrow code "65H" has been set to "10 RON" (previously was assigned to "5 RON") Escrow code "66H" has been set to "20 RON" (previously was assigned to "10 RON") Supported Denominations Set has been updated to "SDS-RON8-R1". 				
<u>FL-RO2130</u>	06/29/18	(M)FL	Romania	FL_BDP
<ol style="list-style-type: none"> Overall acceptance rate has been improved by introducing a new bill processing algorithm and according to the latest samples of street grade bills. DIP Switches settings have been modified (refer to User's guide for details): <ul style="list-style-type: none"> DIP Switch 1.3 includes enable/disable acceptance of old 10 RON (previously assigned to DIP switch 2.1) DIP Switch 2.1 is reassigned to "Four way/One way" banknotes acceptance. 				
<u>FL-RO2125</u>	05/28/14	(M)FL	Romania	FL_BDP
<ol style="list-style-type: none"> Acceptance rate for 1 RON and 10 RON has been improved. Improved holding bills 1,5,10 RON after returning. 				
<u>FL-RO2724</u>	05/06/10	(M)FL	Romania	FL_BDP
Acceptance of 200 and 500 RON has been improved.				
<u>FL-RO2723</u>	09/17/09	(M)FL	Romania	FL_BDP

June 8, 2022

Point to start detecting the end of bill during scanning has been changed in order to improve short coupon rejection (business cards etc.).

<u>FL-RO2722</u>	04/06/09	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

1. Processing of new 10 RON issued in 2008 has been introduced.
2. Acceptance of 1 and 5 RON has been improved based on the latest samples of street grade bills.
3. DIP switch to enable / disable old 10 RON has been introduced.

<u>FL-RO2721</u>	06/24/08	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

Accidental rejections of the bills have been eliminated by correction of preparation procedure for optic signals.

<u>FL-RO2720</u>	05/30/08	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

1. Synchronization by translucent optic signals has been implemented to fix the problem with accepting of transparent plastic bills.
2. Pause state will occur if both Input and Aligning sensors covered.
3. 10 sec timeout implemented in Pause state.

<u>FL-RO2719</u>	04/18/08	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

1. Oval wheel setting time has been increased in order to eliminate the malfunction of MFL's centering mechanism.
2. Stacker cycle has been added in case of rejecting from Stacking state.
3. "Program signature" command has been introduced.
4. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).

<u>FL-RO2717</u>	03/14/07	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

1. Processing of new 200 RON issued in 2006 has been introduced.
2. Processing of all old ROL bills has been disabled.

<u>FL-RO2615</u>	10/21/05	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

Processing of new 1, 5, 10, 50, 100 & 500 RON issued in 2005 has been added.

<u>FL-RO2513</u>	04/19/05	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

Dual bill table has been changed based on customer's latest request.

<u>FL-RO2512</u>	04/18/05 FL_BDP	(M)FL	Romania	
-------------------------	--------------------	-------	---------	--

Acceptance has been improved; processing of 1000000 ROL bill has been added; dual bill table has been implemented.

<u>FL-RO2402</u>	03/02/04	(M)FL	Romania	FL_BDP
-------------------------	----------	-------	---------	--------

Acceptance has been improved; additional check of stacker position has been implemented.

June 8, 2022

FL-RO2401

08/29/03

(M)FL

Romania

FL_BDP

First release.