

# Revision History

13. January 2009

Page 1

No	Item No.	File Name	Release		Country	Comm. Protocol
			Date	Device		
1	<u><a href="#">FL-AU5433</a></u>	FL-AU5AAG4-4.33.hex	12/01/09	FL	Australia	FL-BDG2
		Communication problem with Aristocrat Mk6 platform has been fixed by making interface command UNINHIBIT (F1) applicable in all BV states.				
2	<u><a href="#">FL-AU5432</a></u>	FL-AU5AAG4-4.32.hex	07/03/08	FL	Australia	FL-BDG2
		1. Two-step bill stacking has been implemented in order to improve anti-fishing feature. 2. Communication in Interrupt mode has been improved (FL does not send interrupt request to host after initialization).				
3	<u><a href="#">FL-AU5431</a></u>	FL-AU5AAG4-4.31.hex	11/01/08	FL	Australia	FL-BDG2
		Update for V2.2 version with ASCII barcode data format: 1. Bill table 2 always set (Select Switch disabled). 2. Accepting and rejecting states are not reported in case of feeding error. 3. Request Bill Enables command is not masked with real denomination mask. 4. Barcode from 14 to 18 digits enabled. 5. Stored settings cleared in Service mode.				
4	<u><a href="#">FL-AU5529</a></u>	FL-AU5AAG1-4.29.hex	16/11/07	FL	Australia	FL-BDG2
		Inhibited Flag is set right after Inhibit command(F0) in case if Disabled Flag is already set.				
5	<u><a href="#">FL-AU5527</a></u>	FL-AU5AAG1-4.27.hex	29/10/07	FL	Australia	FL-BDG2
		The new double-bill detection feature has been eliminated.				
6	<u><a href="#">FL-AU5428</a></u>	FL-AU5AAG4-4.28.hex	29/10/07	FL	Australia	FL-BDG2
		The new double-bill detection feature has been eliminated.				
7	<u><a href="#">FL-AU5525</a></u>	FL-AU5AAG1-4.25.hex	04/10/07	FL	Australia	FL-BDG2
		1. Credit recovery option for barcode has been implemented (barcode is treated like a bill). 2. New double-bill detection has been implemented in order to reject double-bills "barcode + bill", "barcode + barcode" and "bill + folded bill put on the front side of the 1st bill". 3. BCD format has been selected for barcode.				
8	<u><a href="#">FL-AU5426</a></u>	FL-AU5AAG4-4.26.hex	04/10/07	FL	Australia	FL-BDG2
		1. New double-bill detection has been implemented in order to reject double-bills "barcode + bill", "barcode + barcode" and "bill + folded bill put on the front side of the 1st bill". 2. ASCII format has been selected for barcode.				
9	<u><a href="#">FL-AU5524</a></u>	FL-AU5AAG1-4.24.hex	17/07/07	FL	Australia	FL-BDG2
		Barcode power recovery has been implemented.				
10	<u><a href="#">FL-AU5523</a></u>	FL-AU5AAG1-4.23.hex	08/06/07	FL	Australia	FL-BDG2
		Barcode data format has been changed from packed BCD to ASCII. Special for the customer: StarGames.				
11	<u><a href="#">FL-AU5522</a></u>	FL-AU5AAG1-4.22	22/08/06	FL	Australia	FL-BDG2
		CRC32 command (0x3B) has been introduced in Service mode in order to provide the way to check authenticity of FL software.				

No	Item No.	File Name	Release		Country	Comm. Protocol	Page
			Date	Device			
			<b>Commentary</b>				2
12	<u>FL-AU5521</u>	FL-AU5AAG1-4.21	06/10/05	FL	Australia	FL-BDG2	
		1. STACKER JAM flag is set to indicate BILL DROP condition in case if bill is lost during rejecting from STACKING state due to cheating or jam. 2. FL does not detect bill removing from the drop cassette if the second bill is inserted.					
13	<u>FL-AU5520</u>	FL-AU5AAG1-4.20	09/05/05	FL	Australia	FL-BDG2	
		Acceptance rate has been enhanced according to the latest samples of street money; triple Scan has been removed.					
14	<u>FL-AU5519</u>	FL-AU5AAG1-4.19	17/12/04	FL	Australia	FL-BDG2	
		Acceptance of 5; 10 & 100 AUD has been improved					
15	<u>FL-AU5509</u>	FL-AU5AAG1-4.18	25/02/04	FL	Australia	FL-BDG2	
		Two bill tables were implemented; Flags STACKER FULL and STACKER JAM united in one event; Flag POWER ON reset after been reported to host; Check Stacker Platform position in Idling.					
16	<u>FL-AU5508</u>	FL-AU5AAG1-4.17	10/12/03	FL	Australia	FL-BDG2	
		Acceptance; part# reported by customer request					