

Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol	Commentary
1	<u>FL-AU2504</u>	FL-AU5AAD0-4.13	11/07/03	FL	AUSTRALIA	FL_BDP	0
2	<u>FL-AU2505</u>	FL-AU5AAD0-4.14	07/19/04	FL	AUSTRALIA	FL_BDP	Acceptance
3	<u>FL-AU2515</u>	FL-AU5AAD0-4.15	12/22/04	FL	AUSTRALIA	FL_BDP	ID code (Boot version) has been changed to B319
4	<u>FL-AU2516</u>	FL-AU5AAD0-4.16	07/18/06	FL	AUSTRALIA	FL_BDP	Acceptance of 5; 10 & 100 AUD has been improved
5	<u>FL-AU2517</u>	FL-AU5AAD0-4.17	07/18/06	FL	AUSTRALIA	FL_BDP	Acceptance rate has been enhanced according to the latest samples of street money; triple Scan has been removed.
6	<u>FL-AU2519</u>	FL-AU5AAD0-4.19.hex	11/28/07	FL	AUSTRALIA	FL_BDP	CRC32 command (0x3B) has been introduced in Service mode in order to provide the way to check authenticity of FL software.
7	<u>FL-AU2522</u>	FL-AU5AAD0-4.22.hex	04/30/08	FL	AUSTRALIA	FL_BDP	1. Processing of "Program signature" command has been brought in. 2. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).
8	<u>FL-AU2525</u>	FL-AU5AAD0-4.25.hex	04/30/08	FL	AUSTRALIA	FL_BDP	1. Anti-fishing capability has been improved by implementation of motor swinging during stacking. 2. Stacker cycle has been added in case of rejecting from stacking state. 3. Second byte of the Request Bill Enables command is not masked with 0xFF. 4. Program CRC in the Version string matches Program Signature (Seed = 0). 5. Acceptance of 20 AUD in High Security mode has been improved.