

Revision History

April 15, 2011

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
1	<u>FL-BW1413</u>	FL-BW5AAJ1-4.13.hex	04/15/11	FL	Botswana	CCNET
		1. Overall acceptance rate has been improved based on the latest samples of street grade bills.				
2	<u>FL-BW1412</u>	FL-BW5AAJ1-4.12.hex	10/30/09	FL	Botswana	CCNET
		1. Processing of new 10, 20, 50, 100 and 200 BWP issued in 2009 has been introduced.				
		2. DIP switch 1.8 enables / disables old BWP.				
3	<u>FL-BW1411</u>	FL-BW4AAJ1-4.11.hex	02/09/09	FL	Botswana	CCNET
		1. Processing of old 10, 50 and 100 BWP has been brought in.				
		2. Stacker cycle has been added in case of rejecting from Stacking state.				
		3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.				
		4. Pause state will occur if both Input and Aligning sensors covered.				
		5. 10 sec. timeout implemented in Pause state.				
		6. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.				
4	<u>FL-BW1410</u>	FL-BW4AAJ1-4.10.hex	03/04/08	FL	Botswana	CCNET
		First release.				