

# Revision History

December 17, 2010

Page 1

| No | Item No.         | File Name  | Release  |        |          | Comm. Protocol |
|----|------------------|--|----------|--------|----------|----------------|
|    |                  |  | Date     | Device | Country  |                |
| 1  | <u>FL-BW2013</u> | FL-BW5AAD0-4.13.hex  | 12/16/10 | FL     | Botswana | FL-BDP         |
|    |                  | Commentary   |          |        |          |                |
|    |                  | 1. Overall acceptance has been improved according to the latest samples of street grade bills.             |          |        |          |                |
|    |                  | 2. Old BWP bills have been excluded from bill processing.  |          |        |          |                |
| 2  | <u>FL-BW2012</u> | FL-BW5AAD0-4.12.hex  | 11/03/09 | FL     | Botswana | FL-BDP         |
|    |                  | 1.Processing of new 10, 20, 50, 100 and 200 BWP issued in 2009 has been introduced.                        |          |        |          |                |
|    |                  | 2.DIP switch 1.8 enables / disables old BWP.   |          |        |          |                |
| 3  | <u>FL-BW2211</u> | FL-BW4AAD2-4.11.hex  | 01/30/09 | FL     | Botswana | FL-BDP         |
|    |                  | 1. Processing of old 10, 50 and 100 BWP has been brought in.   |          |        |          |                |
|    |                  | 2. "Program signature" command has been introduced.  |          |        |          |                |
|    |                  | 3. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).                       |          |        |          |                |
|    |                  | 4. Pause state will occur only if both Input and Aligning sensors covered.                                 |          |        |          |                |
|    |                  | 5. 10 sec. timeout has been implemented in Pause state.  |          |        |          |                |
|    |                  | 6. Checking of drop box presence has been added for the case when returned bill is held in the entry slot. |          |        |          |                |
| 4  | <u>FL-BW2210</u> | FL-BW4AAD2-4.10.hex  | 07/18/07 | FL     | Botswana | FL-BDP         |
|    |                  | First release.   |          |        |          |                |