

Revision History

19. May 2009

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
1	<u>FL-EU1220</u>	FL-EU7AAJ2-4.20.hex	13/05/08	FL	Europe	CCNET
		Commentary				
		1. Oval wheel setting time has been increased in order to eliminate the malfunction of MFL's centering mechanism.				
		2. Stacker cycle has been added in case of rejecting from Stacking state.				
		3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.				
		4. Pause state will occur only if both Input and Aligning sensors covered.				
		5. 10 sec timeout implemented in Pause state.				
2	<u>FL-EU1219</u>	FL-EU7AAJ2-4.19.hex	30/05/07	FL	Europe	CCNET
		Bill processing has been corrected in order to prevent acceptance of folded 10 & 20 EUR with 5 EUR credit.				
3	<u>FL-EU1718</u>	FL-EU7AAJ1-4.18.hex	13/03/07	FL	Europe	CCNET
		Acceptance of 20 EUR has been improved for old sensor sets based on hardware samples received from the customer.				
4	<u>FL-EU1217</u>	FL-EU7AAJ2-4.17	17/08/05	FL	Europe	CCNET
		CashManager (Dallas chip in the cassette) support has been implemented.				
5	<u>FL-EU1716</u>	FL-EU7AAJ1-4.16	08/10/04	FL	Europe	CCNET
		Old bugs in CCNET interface have been fixed				
6	<u>FL-EU1706</u>	FL-EU7AAJ1-4.15	02/09/03	FL	Europe	CCNET
		Fixed the problem with POWER UP state when box's removed. New barcode processing				