## Page 1

## **Revision History**

Release

No	Item No.	File Name Commentary	Date Device	Country	Comm. Protocol
1	FL-MO2616	FL-MO6AAD0-4.16.hex	05/08/09 FL	Macau	FL_BDP
		1. Processing of new MOP bills issued 2009 by Bank of China has been introduced.			
		2. Stacker cycle has been added in case of rejecting from stacking state.			
		3. Second byte of the Request Bill Enables command isn't masked with 0xFF mask.			
		4. Rejecting code "Feed error"(0x75) has been replaced with			
		"Insertion erro	r"(0x71).	•	
			nature" command has	s been introduced.	
					am Signature (Seed=0).
		7. Pause state will occur only if both Input and Aligning sensors covered.			
		8. 10 sec timeout implemented in Pause state.			
		9. Country code has been changed to match with JCM code (0x82).			
					,
2	FL-MO2614	FL-MO6AAD0-4.14.hex	20/06/06 FL	Macau	FL_BDP
		Overall acceptance rate has been improved based on the latest samples of			
		street grade notes.			
		FI 110011 PD 4 40			51 222
3	FL-MO2613	FL-MO6AAD0-4.13	23/03/06 FL	Macau	FL_BDP
		1. Processing of new 10, 20, 100, 500 & 1000 MOP haas been added.			
		2. Part number and boot version information has been added to statistics.			
		3. Statistics counter "Jam at Entrance" has been changed to "Returned bill by			
		Cross Sensor".			
4	FL-MO2611	FL-MO6AAD0-4.11	02/08/05 FL	Macau	FL BDP
		Overall acceptance rate has been improved based on the latest samples of street			
		money.			
5	FL-MO2610	FL-MO6AAD0-4.10	27/10/04 FL	Macau	FL BDP
		First release.	· · · · · ·		· <del></del> ·