

Revision History

May 6, 2010

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
1	<u>FL-RO2724</u>	FL-RO7AAD1-4.24.hex	05/06/10	FL	Romania	FL_BDP
		Acceptance of 200 and 500 RON has been improved				
2	<u>FL-RO2723</u>	FL-RO7AAD1-4.23.hex	09/17/09	FL	Romania	FL_BDP
		Point to start detecting the end of bill during scanning has been changed in order to improve short coupon rejection (business cards etc).				
3	<u>FL-RO2722</u>	FL-RO7AAD1-4.22.hex	04/06/09	FL	Romania	FL_BDP
		1. Processing of new 10 RON issued in 2008 has been introduced. 2. Acceptance of 1 and 5 RON has been improved based on the latest samples of street grade bills. 3. DIP switch to enable / disable old 10 RON has been introduced.				
4	<u>FL-RO2721</u>	FL-RO7AAD1-4.21.hex	06/24/08	FL	Romania	FL_BDP
		Accidental rejections of the bills have been eliminated by correction of preparation procedure for optic signals.				
5	<u>FL-RO2720</u>	FL-RO7AAD1-4.20.hex	05/30/08	FL	Romania	FL_BDP
		1. Synchronization by translucent optic signals has been implemented to fix the problem with accepting of transparent plastic bills. 2. Pause state will occur if both Input and Aligning sensors covered. 3. 10 sec timeout implemented in Pause state.				
6	<u>FL-RO2719</u>	FL-RO7AAD1-4.19.hex	04/18/08	FL	Romania	FL_BDP
		1. Oval wheel setting time has been increased in order to eliminate the malfunction of MFL's centering mechanism. 2. Stacker cycle has been added in case of rejecting from Stacking state. 3. "Program signature" command has been introduced. 4. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).				
7	<u>FL-RO2717</u>	FL-RO7AAD1-4.17.hex	03/14/07	FL	Romania	FL_BDP
		1. Processing of new 200 RON issued in 2006 has been introduced. 2. Processing of all old ROL bills has been disabled.				
8	<u>FL-RO2615</u>	FL-RO6AAD1-4.15	10/21/05	FL	Romania	FL_BDP
		Processing of new 1, 5, 10, 50, 100 & 500 RON issued in 2005 has been added.				
9	<u>FL-RO2513</u>	FL-RO5AAD1-4.13	04/19/05	FL	Romania	FL_BDP
		Dual bill table has been changed based on customer's latest request.				
10	<u>FL-RO2512</u>	FL-RO5AAD1-4.12	04/18/05	FL	Romania	FL_BDP
		Acceptance has been improved; processing of 1000000 ROL bill has been added; dual bill table has been implemented.				
11	<u>FL-RO2402</u>	FL-RO4AAD0-4.11	03/02/04	FL	Romania	FL_BDP
		Acceptance has been improved; additional check of stacker position has been implemented				
12	<u>FL-RO2401</u>	FL-RO4AAD0-4.10	08/29/03	FL	Romania	FL_BDP
		First release				