

Revision History

July 18, 2011

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
		Commentary				
1	<u>FL-ZA7819</u>	FL-ZA5AAS0-5.19.hex	07/18/11	FL	South Africa	CCS-VFM
		1. Processing of stained notes has been improved based on the latest samples of stained bills. 2. Overall acceptance rate has been improved according to the latest samples of street grade bills.				
2	<u>FL-ZA7818</u>	FL-ZA5AAS0-5.18.hex	04/28/10	FL	South Africa	CCS-VFM
		Processing of old 200 ZAR has been disabled.				
3	<u>FL-ZA7817</u>	FL-ZA5AAS0-5.17.hex	03/13/09	FL	South Africa	CCS-VFM
		DIP switch "High Acceptance / High Security" sets acceptance mode for stain notes.				
4	<u>FL-ZA7816</u>	FL-ZA5AAS0-5.16.hex	09/18/08	FL	South Africa	CCS-VFM
		1. Bill processing has been improved to reject stained ZAR notes. 2. Overall acceptance rate has been improved according to the latest samples of street grade bills. 3. Stacker cycle added in case of rejecting from Stacking state. 4. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.				
5	<u>FL-ZA7815</u>	FL-ZA5AAS0-4.15.hex	11/09/06	FL	South Africa	CCS-VFM
		Overall acceptance rate has been improved according to the latest samples of street grade bills.				
6	<u>FL-ZA7814</u>	FL-ZA5AAS0-4.14.hex	08/15/06	FL	South Africa	CCS-VFM
		Message "Drop Box FULL" (0x8D) is used for failures and jam conditions instead of FAILURE(0x8C).				
7	<u>FL-ZA7813</u>	FL-ZA5AAS0-4.13.hex	08/14/06	FL	South Africa	CCS-VFM
		Message "Drop Box removed" (0x8E) is used instead of FAILURE(0x8C).				
8	<u>FL-ZA7812</u>	FL-ZA5AAS0-4.12.hex	07/26/06	FL	South Africa	CCS-VFM
		First release.				