

Revision History

August 20, 2010

Page 1

No	Item No.	File Name	Release		Country	Comm. Protocol
			Date	Device		
1	<u>FL-ZANA2017</u>	FL-ZA5NA5AAD0-5.17.hex	08/17/10	FL	South Africa Namibia	FL_BDP
		Processing of old 200 ZAR has been disabled.				
2	<u>FL-ZANA2016</u>	FL-ZA5NA5AAD0-5.16.hex	04/09/10	FL	South Africa Namibia	FL_BDP
		Acceptance of 10 NAD has been improved based on the latest samples of street grade bills.				
3	<u>FL-ZANA2015</u>	FL-ZA5NA5AAD0-5.15.hex	10/05/09	FL	South Africa Namibia	FL_BDP
		Overall acceptance rate has been improved based on the latest samples of street grade bills.				
4	<u>FL-ZANA2014</u>	FL-ZA5NA5AAD0-5.14.hex	07/08/09	FL	South Africa Namibia	FL_BDP
		Overall acceptance of NAD has been improved according to the latest samples of street grade bills.				
5	<u>FL-ZANA2013</u>	FL-ZA5NA5AAD0-5.13.hex	05/30/09	FL	South Africa Namibia	FL_BDP
		DIP switch "High Acceptance / High Security" sets acceptance mode for stain notes.				
6	<u>FL-ZANA2012</u>	FL-ZA5NA5AAD0-4.12.hex	05/30/08	FL	South Africa Namibia	FL_BDP
		1. Country selection by DIP switch has been excluded. This SW accepts both ZAR and NAD with the same credit for the same denomination.				
		2. Stacker cycle added in case of rejecting from stacking state.				
		3. Second byte of the Request Bill Enables command is not masked with 0xFF.				
		4. Program CRC in the Version string matches Program Signature (Seed = 0).				
		5. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.				
		6. Direction switch has been disabled.				
7	<u>FL-ZN2510</u>	FL-ZA5NA5AAD0-4.10.hex	01/14/08	FL	South Africa Namibia	FL_BDP
		First release.				