

21. May 2009

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
1	<u>FL-CO2520</u>	FL-CO5AAD0-4.20.hex	21/05/09	FL	Colombia	FL_BDP
		Counterfeit protection has been improved according to the latest samples of 5000 & 50000 COP counterfeits.				
2	<u>FL-CO2519</u>	FL-CO5AAD0-4.19.hex	23/10/08	FL	Colombia	FL_BDP
		1. Counterfeit protection has been improved according to the latest samples of 5000 and 10000 COP counterfeits. 2. Stacker cycle has been added in case of rejecting from stacking state. 3. "Program signature" command has been introduced. 4. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71). 5. Pause state will occur only if both Input and Aligning sensors covered. 6. 10 sec timeout implemented in Pause state. 7. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.				
3	<u>FL-CO2518</u>	FL-CO5AAD0-4.18.hex	11/05/07	FL	Colombia	FL_BDP
		Processing of new 2000 COP issued in 2006 has been introduced.				
4	<u>FL-CO2517</u>	FL-CO5AAD0-4.17.hex	19/09/06	FL	Colombia	FL_BDP
		1. Counterfeit protection for 20000 COP has been improved according to the latest samples of "2/5 fake 3/5 good" counterfeits. 2. Counterfeit protection for 10000 COP has been enhanced based on the latest samples of "1/2 fake 1/2 good" counterfeits.				
5	<u>FL-CO2516</u>	FL-CO5AAD0-4.16.hex	26/05/06	FL	Colombia	FL_BDP
		1. Counterfeit protection for 50000 COP has been enhanced according to the latest samples of fake money. 2. Acceptance of 5000, 10000 and 20000 COP has been improved to resolve acceptance issues on old FL units.				
6	<u>FL-CO2515</u>	FL-CO5AAD0-4.15	22/02/06	FL	Colombia	FL_BDP
		1. Protection against glued "half fake - half real" counterfeits has been enhanced based on the latest samples of fake money. 2. Overall acceptance rate has been improved according to the latest samples of street money. 3. Part number and boot version information has been added to statistics. 4. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".				
7	<u>FL-CO2505</u>	FL-CO5AAD0-4.14	21/02/03	FL	Colombia	FL_BDP