

IGT S2000 REEL UPRIGHT



K622-BVD



1. Apply tape to outside bezel per drawing. **This is very important.** Holding the bezel in exactly the correct position for installation of the new display is essential.
2. Open door of machine and locate wire harness plug to validator display. Remove connection.
3. Using Phillips screwdriver, remove two mounting screws.
4. Discard original circuit board and install new LED assembly using same method.
5. Plug in using original wire harness and plug.
6. Close door and system will light the display.
7. Remove tape from front of machine.

