April 15, 2021

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				

BB-UY1184   04/15/21   BB300   Uruguay   CCNET

1.   Acceptance rate for 200 UYU (series 2015) has been improved based on the street grade banknotes (print 2019, Series Letter "G"), received from customer.
2.   Implemented automatic restoring of the recycling cassette capacity limit after restart (power interruption, reset command etc.).

Limitations:
1.   Power recovery is limited because of transparent windows on the banknotes.
2.   Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

BB-UY1183   01/22/21   BB300   Uruguay   CCNET

1.   Processing of new 20 UYU (2020) and 50 UYU (2020) has been introduced.
2.   Acceptance rate has been improved for the following bill types:
      100 UYU (2017), 200 UYU (2006,'09,'11), 500 (2006,'09,'14) and 1000 (2018).
3.   Detection and rejection of plastic/business cards has been improved.

Limitations:
1.   Power recovery is limited because of transparent windows on the banknotes.
2.   Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

BB-UY1182   12/03/19   BB300   Uruguay   CCNET

1.   Processing of commemorative polymer banknote 50 UYU (issued in 2018) has been added.
2.   Overall acceptance rate has been improved.

Limitations:
1.   Power recovery is limited because of transparent windows on the banknotes.
2.   Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

BB-UY1181   08/28/18   BB300   Uruguay   CCNET

1.   Processing of 20, 50, 100, 200, 1000 and 2000 UYU (series 2015) and 2000 UYU (2003) has been added based on the latest samples of street grade bills.
2.   Overall acceptance rate has been improved.
3.   Bill table has been modified to include new denomination of 2000 UYU:
      "Bill type 6" is set to "2000 UYU".
4.   DIP Switches settings have been changed to include new denomination of 2000 UYU:
      DIP Switch 1.7 has been set to "2000 UYU".
5.   Implemented workaround for potential recoverable bezel indication problem in Idling state.
6.   "EMPTY DISPENSER" command is enabled in 0xCA failure state.

---

7. Fixed CCNET command applicability after bills retraction.
That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.

BB-UY1180   10/16/15   BB300   Uruguay   CCNET

First release.
Supported acceptance of 20, 50, 100, 200, 500, 1000 Uruguayan Peso (UYU).