Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
BB-RU1525	07/06/18	BB200G	Russia	CCNET

1. Counterfeit protection has been improved based on scans of 1000 RUB counterfeits received from customer.
2. Acceptance rate for 2000 RUB (2017) has been improved.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1524	05/18/18	BB200G	Russia	CCNET

Counterfeit protection has been improved based on scans of 1000 RUB counterfeits received from customer.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1523	01/25/18	BB200G	Russia	CCNET

1. Processing of two new bill types 200 RUB (2017) and 2000 RUB (2017) has been introduced based on scans received from customer.
2. Bill table has been modified to include new bill types (refer to User's Guide for details):
   "Bill type 3" set to "200 RUB",
   "Bill type 6" set to "2000 RUB".
3. DIP Switches settings have been changed to include new bill types (refer to User's Guide for details):
   DIP Switch 1.4 is set to "200 RUB",
   DIP Switch 1.7 is set to "2000 RUB".
4. Implemented workaround for potential recoverable bezel indication problem in idling state.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1522	03/16/17	BB200G	Russia	CCNET

Detection and rejection of counterfeits 500 RUB has been improved based on the scans received from customer.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1521	05/27/15	BB200G	Russia	CCNET

1. Detection and rejection of counterfeits of 1000 RUB and 5000 RUB has been improved based on the scans received from customer.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1520 05/05/15 BB200G Russia CCNET

1. Detection and rejection of 5000 RUB counterfeits has been improved based on the scans from field.
2. Capacity sensor check in High Security mode has been improved for 1000 RUB ('04, '10) and 5000 RUB ('06, '11).

Limitations:
1. Escrow cassette option is disabled.

BB-RU1519 04/09/15 BB200G Russia CCNET

1. Detection and rejection of counterfeits has been improved.
2. Bill length transfer into chassis was implemented.
3. CCNET_READ_MODULES_ID support enabled for Idling mode.
4. Credit message added when reset on accepting.
5. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.
6. Fixed issues with "BOX REMOVED" reporting.
7. Service mode support is re-enabled.

Limitations:
1. Escrow cassette option is disabled.

BB-RU1518 06/02/14 BB200G Russia CCNET

1. Performance improvement to 1000 and 5000 RUB.
2. Acceptance rate of 100, 1000 and 5000 RUB has been improved based on the latest samples of street grade bills.
3. Old 10 RUB and 50 EUB (series 1997) have been excluded from bill processing.

BB-RU1512 12/21/12 BB200G Russia CCNET

First release for BB200G.