Revision History

Item No. Commentary	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol
BB-USCR1182	03/24/22	BB300	USA + Costa Rica	CCNET

1. Processing of new polymer 1000 CRC (Series C, 2019) and new polymer 10000 CRC (Series B, 2019), both issued in 2021, has been introduced.
2. Processing of old paper 20000 CRC (Series A) has been disabled.
3. Processing of denomination 50000 CRC has been disabled.
4. Classification, identification, and acceptance rate for Costa Rican banknotes have been improved.
5. DIP Switches settings have been modified (refer to User's Guide for details):
   - DIP Switch 1.6 is set to "Reserved" to exclude prohibited 50000 CRC (previously Sw.1.6 was set to enable/disable 50000 CRC).
   - DIP Switch 1.8 is set to enable/disable old paper 2000 CRC (Series A) and 5000 CRC (Series A, B) that will be out of circulation from May 1 of 2022 and March 01 of 2022 accordingly (previously Sw.1.8 was set to "Reserved").
6. Bill Table has been changed to exclude 50000 CRC (refer to User's Guide for details):
   - Bill type "12" is set to "not used" (in previous version Bill Type "12" was set to "50000 CRC").
7. Supported Denomination Set has been updated – for details refer to the document "SDS-USD6CRC5-R1".

Limitations:
1. Jam/Power recovery is limited because of transparent windows on the banknotes.
2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").
3. Maintenance mode (cleaning card) is not supported.

Item No. Commentary	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol
BB-USCR1181	09/08/21	BB300	USA + Costa Rica	CCNET

1. Processing of new 2000, 5000 and 20000 CRC (series 2018, issued in 2020) has been introduced.
2. Processing of old bill types 2 USD, 5 USD, 10 USD, 20 USD, 50 USD and 100 USD, issued before 1996, has been disabled.
3. Acceptance rate for 1000 CRC (2009) has been improved based on the latest samples of street grade banknotes, received from customer.
4. Overall acceptance rate has been improved.
5. Bill table has been modified to exclude 2 USD ("Bill Type 1" has been set to "not used").
6. EMPTY DISPENSER" command has been enabled in 0xCA failure state.
7. Implemented CCNET command applicability after bills retraction.
8. Implemented automatic restoring of the recycling cassette capacity limit after restart (reset command, power interruption, etc.).
9. Implemented workaround for potential recoverable bezel indication problem in idling state.
10. "Anti-fishing" feature has been improved.

Limitations:
1. Jam/Power recovery is limited because of transparent windows on the banknotes.

SUZOHAPP Canada ULC
9225 Leslie St, Units 6-7,
Richmond Hill, ON L4B 3H6,
Canada

T. +1.905.851.9775
info@paycomplete.com
www.paycomplete.com

March 24, 2022

2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").
3. Maintenance mode (cleaning card) is not supported.

BB-USCR1180   01/15/16   BB300   USA + Costa Rica   CCNET

This is a first release for BB300.

Supported acceptance of:
1, 2, 5, 10, 20, 50, 100 United States Dollars (USD),
1000, 2000, 5000, 10000, 20000, 50000 Costa Rican Colon (CRC).

Limitations:
1. Maintenance mode (cleaning card) is not supported.