Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-BY2613**	FL-BY6AAD0-4.13.hex	17/11/09	FL	Belarus	FL_BDP
		1. Motor swinging and additional inspection of Exit sensor during stacking have been implemented to improve anti-cheating algorithm. 2. Stacker cycle has been added in case of rejecting from stacking state. 3. Second byte of the Request Bill Enables command is not masked with 0xFF.				
2	**FL-BY2612**	FL-BY6AAD0-4.12.hex	09/11/06	FL	Belarus	FL_BDP
		Processing of new 100000 BYR issued in 2005 has been introduced.				
3	**FL-BY2501**	FL-BY5AAD0-4.10	01/03/04	FL	Belarus	FL_BDP
		First release				