Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
FL-KR1120	04/30/18	(M)FL	South Korea	CCNET

1. Processing of old 1000 KRW ('83), 5000 KRW ('83,'02), 10000 KRW ('94, '00) has been disabled.
2. Overall acceptance rate has been improved.
3. Barcodes acceptance supported.
4. Greeting message changed to SUZOHAPP.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1119	11/12/09	(M)FL	South Korea	CCNET

Acceptance of 50000 KRW has been improved based on the latest samples of brand new bills.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1118	09/23/09	(M)FL	South Korea	CCNET

Processing of 50000 KRW issued in 2009 has been introduced.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1117	07/09/08	(M)FL	South Korea	CCNET

1. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
2. Pause state will occur only if both Input and Aligning sensors covered.
3. 10 sec timeout implemented in Pause state.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1116	03/04/08	(M)FL	South Korea	CCNET

1. Anti-fishing algorithm has been changed: Synchro sensor is checked now in stacking state instead of Input2 sensor.
2. Stacker cycle has been added in case of rejecting from stacking state.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1115	06/08/07	(M)FL	South Korea	CCNET

Overall acceptance has been improved according to the latest samples of street grade bills.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1114	02/05/07	(M)FL	South Korea	CCNET

Processing of new 1000 & 10000 KRW issued in 2007 has been introduced.

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1113	02/14/06	(M)FL	South Korea	CCNET

1. Processing of new 5000 KRW issued in 2006 has been added.
1. Overall acceptance rate has been enhanced according to the latest samples of street money.
2. Part number and boot version information has been added to statistics.
3. Statistics counter "Jam at Entrance" has been changed to "Returned bill by pass sensor".

Item No.	Release Date	Device	Country	Comm. Protocol
FL-KR1112	07/08/05	(M)FL	South Korea	CCNET

1. Version 1111: When first bill is rejecting or returning and second bill covers the input sensors, the first bill might drop in cashbox during channel cleaning.

2. Version 1112: The situation of bill drop in cashbox has been eliminated.

FL-KR1111 FL-KR3AAJ1-4.11 04/14/05 FL South Korea CCNET
3. Bill drop after rejecting has been eliminated

FL-KR1110	03/10/05	(M)FL	South Korea	CCNET

First release; metal bezel support is implemented.