Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-LT1512**	FL-LT5AAJ1-4.12.hex	07/11/08	FL	Lithuania	CCNET

1. Processing of 200 LTL has been enabled.
2. Processing of 10 and 20 LTL issued in 1997 and 50 LTL issued in 1998 as well as 100 LTL issued in 2007 has been introduced.
3. Stacker cycle has been added in case of rejecting from stacking state.
4. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
5. Pause state will occur only if both Input and Aligning sensors covered.
6. 10 sec timeout implemented in Pause state.
7. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
2	**FL-LT1411**	FL-LT4AAJ1-4.11.hex	03/11/07	FL	Lithuania	CCNET

Processing of new 20 LTL issued in 2007 has been introduced.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
3	**FL-LT1410**	FL-LT4AAJ1-4.10	03/11/05	FL	Lithuania	CCNET

First release.