May 26, 2022

Revision History

Item No. Commentary	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol
FL-RO1125	05/26/22	(M)FL	Romania	CCNET

1. Processing of new denomination 20 RON (Commemorative, issued in 2021) has been introduced.
2. Processing of 1 RON ('18), 5 RON ('18), 10 RON ('08,'18), 50 RON ('18), 100 RON ('18), 200 RON ('18) has been added based on the latest samples of street grade banknotes received from customer.
3. Overall acceptance rate has been improved by introducing a new bill processing algorithm.
4. Bill table has been modified to include the new denomination 20 RON according to the customer's requirements (refer to User's Guide for more details):
   - Bill type "3" is set to "20 RON" (previously was set to "50 RON"),
   - Bill type "4" is set to "50 RON" (previously was set to "100 RON"),
   - Bill type "5" is set to "100 RON" (previously was set to "200 RON"),
   - Bill type "6" is set to "200 RON" (previously was set to "500 RON"),
   - Bill type "7" is set to "500 RON" (previously was "not used").
5. DIP Switches settings have been changed accordingly to include the new 20 RON, upon discussion with the customer (refer to User's Guide for more details):
   - DIP Switch 1.4 is set to enable/disable "20 RON" (previously was set to "50 RON"),
   - DIP Switch 1.5 is set to enable/disable "50 RON" (previously was set to "100 RON"),
   - DIP Switch 1.6 is set to enable/disable "100 RON" (previously was set to "200 RON"),
   - DIP Switch 1.7 is set to enable/disable "200 & 500 RON" both (previously was set to "500 RON" only),
   - DIP Switch 2.1 is reassigned to "Four way/One way" banknotes acceptance,
   - DIP Switch 1.3 includes enable/disable of old 10 RON (previously assigned to DIP switch 2.1).
6. Supported Denominations Set has been updated to "SDS-RON8-R1".

FL-RO1119	06/30/12	(M)FL	Romania	CCNET

1. Logic of Drop Box Full detection has been modified for 1000-notes drop cassettes to prevent premature box full detection.

FL-RO1716	04/30/09	(M)FL	Romania	CCNET

1. Processing of new 10 RON issued in 2008 has been introduced.
2. Acceptance of 1 and 5 RON has been improved based on the latest samples of street grade bills.
3. DIP switch to enable / disable old 10 RON has been introduced.
4. Synchronization by translucent optic signals has been implemented to fix the problem with accepting of transparent plastic RON bills.

FL-RO1715	05/14/08	(M)FL	Romania	CCNET

1. Oval wheel setting time has been increased in order to eliminate the malfunction of MFL's centering mechanism.

SUZOHAPP Canada ULC
9225 Leslie St, Units 6-7,
Richmond Hill, ON L4B 3H6,
Canada

T. +1.905.851.9775
info@paycomplete.com
www.paycomplete.com

May 26, 2022

2. Stacker cycle has been added in case of rejecting from Stacking state.
3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
4. Pause state will occur only if both Input and Aligning sensors covered.
5. 10 sec timeout implemented in Pause state.

FL-RO1714	06/05/07	(M)FL	Romania	CCNET

Logical analysis of bill processing results has been corrected in order to prevent barcode coupons rejections due to "Denomination inhibit" reason.

FL-RO1713	03/15/07	(M)FL	Romania	CCNET

1. Processing of new 200 RON issued in 2006 has been introduced.
2. Processing of all old ROL bills has been disabled.

FL-RO1612	11/03/05	(M)FL	Romania	CCNET

Processing of new 1, 5, 10, 50, 100 & 500 RON issued in 2005 has been added.

FL-RO1411	11/08/04	(M)FL	Romania	CCNET

Acceptance of 500000 ROL bills has been improved.

FL-RO1410	09/03/04	(M)FL	Romania	CCNET

First release.

SUZOHAPP Canada ULC
9225 Leslie St, Units 6-7,
Richmond Hill, ON L4B 3H6,
Canada

T. +1.905.851.9775
info@paycomplete.com
www.paycomplete.com