Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-TH1514**	FL-TH5AAJ1-4.14.hex	06/02/09	FL	Thailand	CCNET

1. Processing of 20 and 50 THB has been introduced.
2. Stacker cycle added in case of rejecting from stacking state.
3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
4. Pause state will occur if both Input and Aligning sensors covered.
5. 10 sec. timeout implemented in Pause state.
6. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.

| 2 | **FL-TH1313** | FL-TH3AAJ1-4.13.hex | 24/07/07 | FL | Thailand | CCNET |

Acceptance of 100 & 1000 THB has been improved according to the latest samples of street grade bills.

| 3 | **FL-TH1312** | FL-TH3AAJ1-4.12.hex | 15/09/06 | FL | Thailand | CCNET |

Processing of new 100 THB issued in 2006 has been introduced.

| 4 | **FL-TH1311** | FL-TH3AAJ1-4.11 | 13/03/06 | FL | Thailand | CCNET |

1. Processing of new 100 & 1000 THB issued in 2005 has been added.
2. Part number and boot versin information has been added to statistics.
3. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".

| 5 | **FL-TH1310** | FL-TH3AAJ1-4.10 | 08/11/04 | FL | Thailand | CCNET |

First release