Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-ZN5514**	FL-ZA5NA5AAG1-5.14.hex	08/17/10	FL	South Africa Namibia	FL-BDG2
		Processing of old 200 ZAR has been disabled.				
2	**FL-ZN5513**	FL-ZA5NA5AAG1-5.13.hex	04/09/10	FL	South Africa Namibia	FL-BDG2
		Acceptance of 10 NAD has been improved based on the latest samples of street grade bills.				
3	**FL-ZN5512**	FL-ZA5NA5AAG1-5.12.hex	10/05/09	FL	South Africa Namibia	FL-BDG2
		1. Overall acceptance rate has been improved based on the latest samples of street grade bills. 2. DIP switch "High Acceptance / High Security" sets acceptance mode for stain notes.				
4	**FL-ZN5511**	FL-ZA5NA5AAG1-4.11.hex	06/04/08	FL	South Africa Namibia	FL-BDG2
		1. Country selection by DIP switch has been excluded. This SW accepts both ZAR and NAD with the same credit for the same denomination. 2. One Way DIP switch has been disabled. 3. In case of fast feeding bill will be rejected only if both Input and Aligning sensors are covered. 4. FL detects cash box removal when the bill has been rejected or returned and is held at entry sensor. 5. Accepting and rejecting states will not be reported in case of feeding error. 6. Request Bill Enables command is not masked with real denominations mask. 7. Barcode acceptance for 14 to 18-digits barcodes has been enabled. 8. Stored settings cleared in Service mode.				
5	**FL-ZN5510**	FL-ZA5NA5AAG1-4.10.hex	09/20/07	FL	South Africa Namibia	FL-BDG2
		First release.				