Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol	Commentary
1	**FL-HK5501**	FL-HK5AAG1-4.10	03/30/04	FL	HK	FL-BDG2	*First release*
2	**FL-HK5513**	FL-HK5AAG1-4.13	08/08/05	FL	HK	FL-BDG2	*$10 Hong Kong Dollars bills have been removed from bill table.*
3	**FL-HK5602**	FL-HK6AAG1-4.11	03/29/04	FL	HK	FL-BDG2	*New $100 and $500 bills have been added as well as $10 bills*
4	**FL-HK5603**	FL-HK6AAG1-4.12	06/22/06	FL	HK	FL-BDG2	*New $100 and $500 bills have been added as well as $10 bills*
5	**FL-HK5613**	FL-HK6AAG1-4.13	09/12/05	FL	HK	FL-BDG2	*1. Processing of new 1000 HKD bills has been added.* *2. Overall acceptance has been improved based on the latest samples of street money.* *3. Processing of 10 HKD has been restored.*
6	**FL-HK5614**	FL-HK6AAG1-4.14	02/07/06	FL	HK	FL-BDG2	*1.STACKER JAM flag is set to indicate BILL DROP condition in case if the bill lost during rejecting from STACKING state due to cheating or jam.* *2. FL does not detect bill removing from the drop cassette if the second bill is inserted.*
7	**FL-HK5615**	FL-HK6AAG1-4.15	06/22/06	FL	HK	FL-BDG2	*1. Processing of new 20 HKD and 50 HKD issued in 2003 has been added.* *2. Part number and boot versin information has been added to statistics.* *3. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".*
8	**FL-HK5616**	FL-HK6AAG1-4.16.hex	10/19/06	FL	HK	FL-BDG2	*Overall acceptance rate has been improved according to the latest samples of street grade bills.*
9	**FL-HK5617**	FL-HK6AAG1-4.17.hex	07/13/07	FL	HK	FL-BDG2	*Barcode acceptance has been improved by increasing the size of internal barcode buffer.*
10	**FL-HK5618**	FL-HK6AAG1-4.18.hex	07/13/07	FL	HK	FL-BDG2	*1.Barcode data format has been changed from packed BCD to ASCII.* *2.Credit Recovery option for barcode has been implemented.*