Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-NZ1525**	FL-NZ5AAJ1-4.25.hex	20/02/09	FL	New Zealand	CCNET
		1. Acceptance of 100 NZD has been improved based on the latest samples of street grade bills. 2. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.				
2	**FL-NZ1524**	FL-NZ5AAJ1-4.24.hex	02/05/08	FL	New Zealand	CCNET
		1. Stacker cycle added in case of rejecting from stacking state. 2. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions. 3. Pause state will occur if both Input and Aligning sensors covered. 4. 10 sec timeout implemented in Pause state.				
3	**FL-NZ1523**	FL-NZ5AAJ1-4.23	29/08/06	FL	New Zealand	CCNET
		Overall acceptance has been improved according to the latest samples of street money				
4	**FL-NZ1522**	FL-NZ5AAJ1-4.22	19/09/05	FL	New Zealand	CCNET
		Prevention of bill drop from FL during bill returning or rejecting has been implemented.				
5	**FL-NZ1513**	FL-NZ5AAJ1-4.21	11/06/04	FL	New Zealand	CCNET
		Acceptance of 50 & 100 NZD has been improved				
6	**FL-NZ1512**	FL-NZ5AAJ1-4.20 0	01/08/03	FL	New Zealand	CCNET