Revision History

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
		Commentary				
1	**FL-RU5529**	FL-RU6AAG1-5.29.hex	22/09/08	FL	Russia	FL-BDG2

1. Counterfeit protection has been improved according to the latest samples
   of glued 1000 & 5000 RUB bills.
2. Overall acceptance has been improved based on the latest samples of street
   grade bills.
3. Accepting and rejecting states are not reported in case of feeding error.
4. Request Bill Enables command is not masked with real denomination mask.
5. Barcodes from 14 to 18 digits have been enabled.
6. Cassette precense checking added when bill is held in the entry slot.
7. Stored settings are cleared in Service mode.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
2	**FL-RU5528**	FL-RU6AAG1-5.28.hex	25/11/06	FL	Russia	FL-BDG2

Processing of new 5000 RUB issued in 2006 has been introduced.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
3	**FL-RU5527**	FL-RU5AAG1-5.27.hex	07/04/06	FL	Russia	FL-BDG2

1. Counterfeit protection has been enhanced according to the latest
   Over-painted fakes.
2. Boot vesion and part number have been added to statistics.
3. Statistical counter "Jam at Entrance" has been changed to "Return bills
   by pass sensor".

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
4	**FL-RU5526**	FL-RU5AAG1-4.26.hex	09/09/05	FL	Russia	FL-BDG2

1.STACKER JAM flag is set to indicate BILL DROP condition in case if the bill
lost during rejecting from STACKING state due to cheating or jam.
2. FL does not detect bill removing from the drop cassette if the second
   bill is inserted.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
5	**FL-RU5525**	FL-RU5AAG1-4.25	12/11/04	FL	Russia	FL-BDG2

Processing of 10; 50; 100; 500; 1000 Rubles issued in 2004 has been added.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
6	**FL-RU5515**	FL-RU5AAG1-4.24	16/04/04	FL	Russia	FL-BDG2

Improved acceptance; problem with RETRANSMIT command in V2.2 interface has been
fixed

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
7	**FL-RU5514**	FL-RU5AAG1-4.23	19/02/04	FL	Russia	FL-BDG2

1) Flags STACKER FULL and STACKER JAM united in one event 2)Flag POWER ON reset
after been reported to host 3)Country code is 'RUB' 4)Check Stacker Platform pos
ition in Idling.

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
8	**FL-RU5513**	FL-RU5AAG1-4.22	13/02/04	FL	Russia	FL-BDG2

Customer tesitng results

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
9	**FL-RU5507**	FL-RU5AAG1-4.16	24/11/03	FL	Russia	FL-BDG2

Reverse order of Program revision - command D8. Add Returned event after bill re
jecting.