

Revision History

December 17, 2013

Page 1

No	Item No.	File Name	Release Date	Device	Country	Comm. Protocol
1	<u>BB-BB1170</u>	FL-BB4AAJ1-1.70-BB.hex	12/17/13	BB	Barbados	CCNET
		Commentary				
		1. Processing of new 2, 5, 10 and 20 BBD issued in 2013 has been introduced. 2. All the latest software improvements in preparation for the divestiture of Bill-to-Bill product line have been incorporated.				
2	<u>BB-BB1150</u>	FL-BB4AAJ1-1.50-BB	03/10/06	BB	Barbados	CCNET
		First release. Distinctive features are: 1. Metal bezel support. 2. Barcode recognition. 3. Jam (credit loss) prevention. 4. Chassis soft download via CCNET. 5. Improved short bill returning. 6. Pass sensor's processing during bill packing has been improved to prevent rejection of single bills. 7. 'SET OPTIONS' and 'GET OPTIONS' commands have been added to CCNET. 8. Processing of the following options has been implemented: 'LED BV INHIBIT' -> 0 - LED is red in BV_INHIBIT state; 1 - LED is turned off 'KEEP BILL' -> 0 - bill will be dropped after returning; 1 - bill will be held 'LOOK TAPE' -> enhanced processing of pass sensor (0 - OFF, 1 - ON) 'TURN SWITCH' -> switch turning after bill packing (0 - OFF, 1 - ON) 9. Loss of cassette setting "Not Assigned" after RESET has been eliminated. 10. Control of triangle wheel in metal bezel during bill accepting has been improved to prevent the bill sticking. 11. Control of thermo heater in metal dispenser has been added. 12. Enhance the algorithm of BB self-testing: if cassette(s) is(are) removed, software has to skip the algorithm of "device recovery after POWER DOWN" and turn to the regular self-testing. 13. Set higher priority to the indication of "BOX REMOVED" state. 14. Make "RECYCLING CASSETTE STATUS" request accessible only in IDLING, DISABLED, ESCROW states (according to "CashCode NET" description). 15. Do not erase an IDENTIFICATION NUMBER of BB unit in statistics after download to the validating head the software designed for another country.				