

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BB-EUPL1104</u></b>	08/30/17	BB300XE	Euro + Poland	CCNET
<ol style="list-style-type: none"> <li>1. Detection and rejection of counterfeits 50 EUR (2002) has been improved based on samples received from the field.</li> <li>2. Processing of new 50 EUR (2017) has been introduced, including support of banknotes with "R"-code, printed by BUNDESDRUCKEREI.</li> <li>3. Processing of new 500 PLN (2017) has been introduced and support of 200 PLN (2016) has been added.</li> <li>4. Bill table has been modified to include 500 PLN ("Bill type 12" is set to "500 PLN").</li> <li>5. Detection and rejection of paper infused EUR banknotes has been implemented.</li> <li>6. Implemented support for new BCU (Box Control Unit) with increased stacking force.</li> <li>7. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.</li> </ol>				
<b><u>BB-EUPL1103</u></b>	08/10/15	BB300XE	Euro + Poland	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 20 EUR (2015) has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. Rejection of folded EUR banknotes has been improved to prevent cross-validation.</li> <li>4. Detection and rejection of EUR counterfeits has been improved.</li> <li>5. "EMPTY DISPENSER" command is re-enabled in 0xCA failure state.</li> <li>6. Fixed Power recovery issues during stacking.</li> <li>7. Fixed missing message about unloaded bills before "BOX FULL" message.</li> <li>8. Corrected processing of Statistics counters for bills, packed into cassette after "Power cut during stacking".</li> <li>9. Eliminated occasional false "BOX FULL" reports.</li> <li>10. Improved stacking procedure for bills packed into Drop Box.</li> <li>11. Eliminated false Power recovery report during initialization after BOX FULL message.</li> </ol>				
<b><u>BB-EUPL1102</u></b>	03/13/15	BB300XE	Euro + Poland	CCNET
<ol style="list-style-type: none"> <li>1. Overall acceptance rate has been improved.</li> <li>2. Rejection of folded new 10 Euro has been improved to prevent cross-validation.</li> <li>3. Detection and rejection of counterfeits has been improved.</li> <li>4. Diagnostics fixed.</li> <li>5. "CashCode" was changed to "Suzo-Happ Group" everywhere.</li> <li>6. Bill length transfer into chassis was implemented.</li> <li>7. DISPENSED message added in case of Dispenser failure during Dispensing operation.</li> <li>8. CCNET_READ_MODULES_ID support became enabled for Idling mode.</li> <li>9. Credit message added when reset on accepting.</li> <li>10. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.</li> <li>11. Optical length filter was implemented.</li> <li>12. Fixed issues with "BOX REMOVED" reporting.</li> <li>13. Service mode support is re-enabled.</li> </ol>				

August 30, 2017

**BB-EUPL1101**

10/17/14

BB300XE

Euro + Poland

CCNET

First release for BB300XE.