

March 4, 2022

## Revision History

Item No.	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol
<b>BB-GT1183</b>	03/04/22	BB300	Guatemala	CCNET
1. The new 20 GTQ (Commemorative, issued in September of 2021) has been introduced. 2. Overall acceptance has been improved.  Limitations: 1. Power recovery is limited because of transparent windows on the banknotes. 2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").				
<b>BB-GT1182</b>	07/14/21	BB300	Guatemala	CCNET
1. Processing of 5 GTQ (2014, 2018), 10 GTQ (2018), 50 GTQ (2018) and 100 GTQ (2015, 2018, 2020) has been added. 2. Acceptance rate for 20 GTQ (2017) has been improved based on the latest samples of street grade banknotes received from customer. 3. Overall acceptance rate has been improved. 4. Implemented automatic restoring of the recycling cassette capacity limit after restart (power interruption, reset command, etc.). 5. Implemented workaround for potential recoverable bezel indication problem in idling state. 6. Eliminated false bills rejection accompanied by "CHEATED" message for 100 GTQ.  Limitations: 1. Power recovery is limited because of transparent windows on the banknotes. 2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").				
<b>BB-GT1181</b>	10/16/17	BB300	Guatemala	CCNET
1. Processing of new 20 GTQ (2017) has been introduced. 2. Support of 5 GTQ (2012) and 10 GTQ (2014) has been added. 3. Counterfeit protection has been improved based on the latest samples of 10 GTQ (2014) counterfeits. 4. Overall acceptance rate has been improved according to the latest samples of street grade bills. 5. "EMPTY DISPENSER" command is enabled in 0xCA failure state. 6. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.  Limitations: 1. Power recovery is limited because of transparent windows on the banknotes. 2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").				

March 4, 2022

**BB-GT1180**

07/13/15

BB300

Guatemala

CCNET

1. Processing of 100 GTQ and 200 GTQ has been introduced.
2. Overall acceptance rate has been improved.
3. Eliminated occasional false "BOX FULL" reports.
4. Added jam recovery functions (in unloading and dispensing).
5. "CashCode" was changed to "SUZOHAPP" everywhere.
6. Bill length transfer into chassis was implemented.
7. DISPENSED message added in case of Dispenser failure during Dispensing operation.
8. CCNET\_READ\_MODULES\_ID command enabled for Idling mode.
9. Credit message added when reset on accepting.
10. Fixed issues with "BOX REMOVED" reporting.
11. Enabled self-test for magnetic sensors.
12. Infinite initialization cycle is fixed. Root cause found and resolved by putting a boundary check to prevent memory corruption during scanning.
13. Maintenance mode (cleaning card) support added.
14. Fixed Power recovery issue during stacking.
15. Fixed missing message about unloaded bills before BOX FULL message.

**BB-GT1170**

11/30/13

BB300

Guatemala

CCNET

First release.