

Revision History

| Item No. | Release Date | Device | Country | Comm. Protocol |
|---|--------------|--------|---------|----------------|
| Commentary | | | | |
| <u>BB-NO1180</u> | 09/12/17 | BB300 | Norway | CCNET |
| <ol style="list-style-type: none">1. Processing of new 100 NOK (2017) and 200 NOK (2017) has been introduced.2. Bill-to-Bill's response to command "Get Bill Table" (0x41H) has been modified to report Currency code instead of Country code.3. MODULE IDENTIFICATION command has been enabled in IDLING state.4. Introduced Jam Recovery feature (in Accepting, Unloading and Dispensing).5. Feed level capability has been introduced.6. "EMPTY DISPENSER" command is enabled in 0xCA failure state.7. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.8. Extended format of Statistics has been introduced.9. Diagnostic feature is enabled.10. Maintenance mode (cleaning card) support added.11. Greeting message changed to "SUZOHAPP". | | | | |
| <u>BB-NO1153</u> | 02/12/07 | BB300 | Norway | CCNET |
| First release for BB300. | | | | |