

# Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BB-OM1183</u></b>	09/14/21	BB300	Oman	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 0.1 OMR (100 Baisa), 0.5 OMR, 1 OMR, 5 OMR, 10 OMR, 20 OMR (series 2020, issued in 2021) and 50 OMR (series 2020, issued in 2020) has been introduced.</li> <li>2. Processing of 50 OMR (series 2019, issued in 2019) has been added.</li> <li>3. Acceptance rate for 1 OMR (2005) and 50 OMR (2010) has been improved.</li> <li>4. Implemented automatic restoring of the recycling cassette capacity limit after restart (reset command, power interruption, etc.).</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Escrow cassette option is disabled.</li> <li>2. 50 OMR cannot be recycled and will be packed into Drop Box.</li> <li>3. Power Recovery is limited because of transparent windows on the banknotes.</li> <li>4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").</li> </ol>				
<b><u>BB-OM1182</u></b>	07/03/18	BB300	Oman	CCNET
<ol style="list-style-type: none"> <li>1. Fixed situation when unit could enter endless initialization loop.</li> <li>2. Implemented workaround for potential recoverable bezel indication problem in Idling state.</li> <li>3. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Escrow cassette option is disabled.</li> <li>2. 50 OMR cannot be recycled and will be packed into Drop Box.</li> <li>3. Power Recovery is limited because of transparent windows on the banknotes.</li> <li>4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").</li> </ol>				
<b><u>BB-OM1181</u></b>	02/03/17	BB300	Oman	CCNET
<ol style="list-style-type: none"> <li>1. Processing of 1 OMR (2015) has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. "EMPTY DISPENSER" command has been enabled in 0xCA failure state.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Escrow cassette option is disabled.</li> <li>2. 50 OMR cannot be recycled and will be packed into Drop Box.</li> <li>3. Power Recovery is limited because of transparent windows on the banknotes.</li> </ol>				
<b><u>BB-OM1180</u></b>	12/04/14	BB300	Oman	CCNET
<p>First release.</p> <p>Distinctive features are:</p>				

---

September 14, 2021

1. Barcode recognition.
2. Maintenance (cleaning card) support implemented with chassis BB-BC714745 or later.
3. 0.1 (100 Baisa), 0.5, 1, 5, 10, 20 and 50 OMR acceptance supported.

Limitations:

1. Escrow cassette option is disabled.
2. 50 OMR cannot be recycled and will be packed into Drop Box.
3. Power Recovery is limited because of transparent windows on the banknotes.