

# Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>Commentary</b>				
<b><u>BB-SA1183</u></b>	05/28/21	BB300	Saudi Arabia	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new polymer 5 SAR (2020) and new 20 SAR (2020, Commemorative) has been introduced.</li> <li>2. Processing of old bill types 1, 5, 10, 50 and 100 SAR, issued in 1983-1984, has been disabled.</li> <li>3. Acceptance rate for 1 SAR ('2007,'09), 10 SAR ('2007,'09) and 100 SAR ('2003) has been improved.</li> <li>4. Implemented automatic restoring of the recycling cassette capacity limit after restart ("Reset" command, power interruption, etc.).</li> <li>5. Implemented workaround for potential recoverable bezel indication problem in Idling state.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance Mode can be enabled using Communication Protocol only.</li> <li>2. Power recovery is limited because of transparent windows on the banknotes.</li> <li>3. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").</li> </ol>				
<b><u>BB-SA1182</u></b>	10/11/17	BB300	Saudi Arabia	CCNET
<ol style="list-style-type: none"> <li>1. Processing of new 5, 10, 50, 100 and 500 SAR series 2016 has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> <li>3. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance Mode can be enabled using Communication Protocol only.</li> </ol>				
<b><u>BB-SA1181</u></b>	05/16/16	BB300	Saudi Arabia	CCNET
<ol style="list-style-type: none"> <li>1. Acceptance rate for 50 SAR ('2007,'09) and 500 SAR ('2007) has been improved based on scans received from the field.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance Mode can be enabled using Communication Protocol only.</li> </ol>				
<b><u>BB-SA1180</u></b>	04/27/16	BB300	Saudi Arabia	CCNET
<ol style="list-style-type: none"> <li>1. Processing of 1 SAR (2007, '09) has been introduced.</li> <li>2. Added support of 50 SAR, printed in 2009.</li> <li>3. Overall acceptance rate has been improved.</li> <li>4. Introduced Jam Recovery feature (in Accepting, Unloading and Dispensing).</li> <li>5. Maintenance mode (cleaning card) support added.</li> <li>6. "EMPTY DISPENSER" command has been enabled in 0xCA failure state.</li> <li>7. New format of Statistics supported.</li> <li>8. "CashCode" was changed to "Suzo-Happ Group" everywhere.</li> </ol> <p>Limitations:</p> <ol style="list-style-type: none"> <li>1. Maintenance Mode can be enabled using Communication Protocol only.</li> </ol>				

May 28, 2021

---

**BB-SA1163**

11/25/09

BB300

Saudi Arabia

CCNET

First release for BB300.