

August 21, 2017

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-SE1182</u>	08/21/17	BB300	Sweden	CCNET
<ol style="list-style-type: none"> 1. Processing of old 100 and 500 SEK (series 2001) has been disabled. 2. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser. 				
<u>BB-SE1181</u>	06/10/16	BB300	Sweden	CCNET
<ol style="list-style-type: none"> 1. Processing of new 100 SEK (2016) and 500 SEK (2016) has been introduced. 2. Processing of old 20 SEK (1997), 50 SEK (2006) and 1000 SEK (2006) has been disabled. 3. "EMPTY DISPENSER" command has been enabled in 0xCA failure state. 				
<u>BB-SE1180</u>	12/09/15	BB300	Sweden	CCNET
<ol style="list-style-type: none"> 1. Processing of new 20 SEK (2015), 50 SEK (2015), 200 SEK (2015) and 1000 SEK (2015) has been introduced. 2. Processing of 50 SEK (1996) has been disabled. 3. Overall acceptance rate has been improved. 4. Bill Table has been changed because of introduction of 200 SEK (2015) (refer to User's Guide for details). 5. Maintenance mode (cleaning card) support added. 6. Introduced Jam Recovery feature (in Accepting, Unloading and Dispensing). 				
<u>BB-SE1152</u>	08/17/06	BB300	Sweden	CCNET
First Release: <ol style="list-style-type: none"> 1. Metal bezel support. 2. Barcode recognition. 3. Jam (credit loss) prevention. 4. Chassis soft download via CCNET. 5. Improved short bill returning. 				