

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-UA1182</u>	05/04/21	BB300	Ukraine	CCNET
<ol style="list-style-type: none"> Processing of new bill types 50 UAH and 200 UAH (series 2019, issued in 2020) has been introduced. Processing of new denomination 1000 UAH (issued in 2019) has been introduced. Processing of old banknotes 1 UAH ('04), 50 UAH ('96), 100 UAH ('96) and 200 UAH ('01) has been disabled. Overall acceptance rate has been improved based on the latest samples of street grade banknotes received from customer. Implemented automatic restoring of the recycling cassette capacity limit after restart (power interruption, reset command, etc.). Bill table has been modified to include the new denomination of 1000 UAH (refer to User's Guide for the details): <ul style="list-style-type: none"> - Bill type "9" has been set to "1000 UAH" (previously was set to "0"). DIP Switches settings have been changed to include the new denomination of 1000 UAH (refer to User's Guide for the details): <ul style="list-style-type: none"> - DIP Switch 1.1 has been assigned to 1, 2, 5 UAH (previously was assigned to "1 UAH"). - DIP Switch 1.2 has been assigned to 10 UAH (previously was assigned to "2 UAH"). - DIP Switch 1.3 has been assigned to 20 UAH (previously was assigned to "5 UAH"). - DIP Switch 1.4 has been assigned to 50 UAH (previously was assigned to "10, 20 UAH"). - DIP Switch 1.5 has been assigned to 100 UAH (previously was assigned to "50 UAH"). - DIP Switch 1.6 has been assigned to 200 UAH (previously was assigned to "100 UAH"). - DIP Switch 1.7 has been assigned to 500 UAH (previously was assigned to "200 UAH"). - DIP Switch 1.8 has been assigned to 1000 UAH (previously was assigned to "500 UAH"). <p>Limitations:</p> <ol style="list-style-type: none"> Maintenance Mode can be enabled using Communication Protocol only. Diagnostics is disabled. 				
<u>BB-UA1181</u>	04/01/19	BB300	Ukraine	CCNET
<ol style="list-style-type: none"> Processing of 20 UAH issued in 2018 has been introduced. Implemented workaround for potential recoverable bezel indication problem in Idling state. <p>Limitations:</p> <ol style="list-style-type: none"> Maintenance Mode can be enabled using Communication Protocol only. Diagnostics is disabled. 				
<u>BB-UA1180</u>	08/14/17	BB300	Ukraine	CCNET
<p>Project is based on version BB-UA1157.</p> <ol style="list-style-type: none"> Processing of 20 UAH (2016), 100 UAH (2014) and 500 UAH (2015) has been added. Processing of old 1, 2, 5, 10 and 20 UAH, issued before 2003, has been disabled. MODULE IDENTIFICATION command has been enabled in IDLING state. Introduced Jam Recovery feature (in Accepting, Unloading and Dispensing). 				

May 4, 2021

5. Feed level capability has been introduced.
6. "EMPTY DISPENSER" command is enabled in OxC A failure state.
7. Fixed CCNET command applicability after bills retraction.
That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser (attempts to accept bill, dispense bills, possibility of jams in dispenser).
8. Extended format of Statistics has been introduced.
9. Maintenance mode (cleaning card) support added.
10. Greeting message changed to "SUZOHAPP".

Limitations:

1. Maintenance Mode can be enabled using Communication Protocol only.
2. Diagnostics is disabled.