April 26, 2019

## **Revision History**

ltem No.		Release Date	Device	Country	Comm. Protoco	
Со	nmentary					
BE-EUGB	NI1504	04/26/19	BB200G_SS	Europe + Great Britain + Northern Ireland	CCNET	
1.	Processing of new banknotes has been introduced:					
	- 5, 10 GBP	(2019, Bank of Irel	and);			
		(2019, Ulster Bank				
		)19, Danske Bank);	;			
		00 EUR (2019).				
2.	-			and 10 GBP (2002, Bank of England) has been d	lisabled.	
3.		-		mproved for EUR banknotes.		
4.	•	tance rate has bee	•			
5.			-	vith Smart Stick for B2B200G.		
6.	Implemented	remote Chassis so	•			
7.				rted prematurely in rare situations.		
				rted prematurely in rare situations. Ie bezel indication problem in Idling state.		
7. 8.						
7. 8.	Implemented mitations:		otential recoverat			
7. 8. Li	Implemented mitations: Escrow casset	workaround for potential terms of the second s	otential recoverat			
7. 8. Li 1. 2.	Implemented mitations: Escrow casset Power recove	workaround for potential terms of the second s	otential recoverat	le bezel indication problem in Idling state.	CCNET	
7. 8. 1. 2. <b>3E-EUGB</b>	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r	workaround for portion is disable ry is limited becau 04/28/17	otential recoverab ed. Ise of transparent BB200G_SS	le bezel indication problem in Idling state. windows on the banknotes.		
7. 8. 1. 2. <b>3E-EUGB</b> 1.	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN	workaround for po te option is disable ry is limited becau 04/28/17 new 50 EUR (2017) NDESDRUCKEREI.	otential recoverat ed. ise of transparent BB200G_SS has been introdu	le bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland		
7. 8. 1. 2. 3 <b>E-EUGB</b> 1.	Implemented mitations: Escrow casset Power recove MI1503 Processing of r printed by BUN Processing of r	workaround for po te option is disable ry is limited becau 04/28/17 new 50 EUR (2017) NDESDRUCKEREI. new polymer 10 GE	otential recoverat ed. Ise of transparent BB200G_SS has been introdu BP (2017, Bank of 1	vie bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co		
7. 8. 1. 2. 3E-EUGB 1. 2. 3.	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN Processing of r	workaround for po te option is disable ry is limited becau 04/28/17 new 50 EUR (2017) NDESDRUCKEREI. new polymer 10 GE	otential recoverat ed. ise of transparent BB200G_SS has been introdu 3P (2017, Bank of 1 16, Bank of Englan	le bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added.		
7. 8. 1. 2. 3 <b>E-EUGB</b> 1. 2. 3. 4.	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN Processing of r Processing of p	workaround for particle option is disable ry is limited becau 04/28/17 NDESDRUCKEREI. NDESDRUCKEREI. new polymer 10 GE polymer 5 GBP (202	otential recoverations ed. Ise of transparent BB200G_SS has been introdu BP (2017, Bank of I 16, Bank of Englan of England) has be	le bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added.		
7. 8. 1. 2. 3 <b>E-EUGB</b> 1. 2. 3. 4.	Implemented mitations: Escrow casset Power recove MI1503 Processing of r printed by BUN Processing of r Processing of p Processing of 5 Overall accepti	workaround for particle option is disable ry is limited becau 04/28/17 NDESDRUCKEREI. NEW polymer 10 GE polymer 5 GBP (202 5 GBP (2002, Bank ing rate has been i	otential recoveration ed. Ise of transparent BB200G_SS has been introdu BP (2017, Bank of I 16, Bank of Englan of England) has be mproved.	le bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added.		
7. 8. 1. 2. 3E-EUGB 1. 2. 3. 4. 5.	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN Processing of r Processing of r Processing of s Overall accepti Detection and	workaround for particle option is disable ry is limited becau 04/28/17 NDESDRUCKEREI. NEW polymer 10 GE polymer 5 GBP (202 5 GBP (2002, Bank ing rate has been i	otential recoverat ed. Ise of transparent BB200G_SS has been introdu 3P (2017, Bank of I 16, Bank of Englan of England) has be mproved. infused EUR bank	ele bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added. een disabled.		
7. 8. 1. 2. <b>BE-EUGB</b> 1. 2. 3. 4. 5. 6. 7.	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN Processing of r Processing of r Processing of s Overall accepti Detection and	workaround for particle option is disable ry is limited becau 04/28/17 NDESDRUCKEREI. NDESDRUCKEREI. NDESDRUCKEREI. Solymer 5 GBP (2002, Bank Solymer 5 GBP (2002, Bank) Solymer 10 GE Solymer 5 GBP (2002, Bank) Solymer 5 GBP (2002, Bank)	otential recoverat ed. Ise of transparent BB200G_SS has been introdu 3P (2017, Bank of I 16, Bank of Englan of England) has be mproved. infused EUR bank	ele bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added. een disabled.		
7. 8. 1. 2. 3E-EUGB 1. 2. 3. 4. 5. 6. 7. Lim	Implemented mitations: Escrow casset Power recove SNI1503 Processing of r printed by BUN Processing of r Processing of r Processing of s Overall accepti Detection and Overall accepti	workaround for particle option is disable ry is limited becau 04/28/17 NDESDRUCKEREI. NDESDRUCKEREI. NDESDRUCKEREI. Solymer 5 GBP (2002, Bank Solymer 5 GBP (2002, Bank) Solymer 10 GE Solymer 5 GBP (2002, Bank) Solymer 5 GBP (2002, Bank)	otential recoveration ed. Ise of transparent BB200G_SS has been introduce BP (2017, Bank of I 16, Bank of Englan of England) has be mproved. infused EUR bank in improved.	ele bezel indication problem in Idling state. windows on the banknotes. Europe + Great Britain + Northern Ireland ced, including support of banknotes with "R"-co England) has been introduced. d) has been added. een disabled.		

- 1. Processing of new 20 EUR (2015) has been introduced.
- 2. Overall acceptance rate has been improved.
- 3. Rejection of folded EUR banknotes has been implemented to prevent cross-validation.
- 4. Detection and rejection of EUR counterfeits has been improved.
- 5. Fixed missing message about unloaded bills before BOX FULL message.
- 6. Eliminated false bills rejection accompanied by "CHEATED" message.
- 7. Removed unreadable symbols in the greeting message on digital display bezel.

## **S**UZOHAPP

April 26, 2019

8. Service mode support is re-enabled.

Limitations:

1. Escrow cassette option is disabled.

BE-EUGBNI1501	09/16/14	BB200G_SS	Europe + Great Britain + Northern Ireland	CCNET
Introduction of new	10 Euro.			

Limitations:

1. Escrow cassette option is disabled.